

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 041030

PRIMARY CORNER DESCRIPTION SW Cor. James Odles DLC #41

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Contract dated Sept. 1856 (DCSO DLC records Pg 175 ----- Set post SW cor. Claim 41, from which A fir, 15" dia., bears N.27°E., 23 lks. A fir, 15" dia., bears N.52°W., 15 lks.	
Douglas Co. Surveyors Office - V.R. Tracy - Feb. 1965 - C.S. File 53/47-50 ----- Not found.	
Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 12/8/2015 (Filed 1/27/2021) - C.S. File 67/48-7 ----- Found - No monument fd. Original BT, a 20"x2' high rotted and broken fir stump bears N.52°W., 9.9 feet with scribe mark "T" visible with an axe notch Set - At the record bearing and distance from the found original BT I set a 1¼"x32" iron post, 26" in the ground with a 2½" brass cap marked: DOUGLAS COUNTY SURVEYOR T25S SW DLC 41 2015 New - A 15"x4½' high D.Fir stump bears S.76½°E., 24.2 ft. scribed "SW DLC 41 CS BT" A 32"x4½' high D.Fir stump bears S.15°W., 24.0 ft scribed "SW DLC 41 CS BT" A 10"x3½' high D.Fir stump bears S.89°W., 20.4 ft. scribed "SW DLC 41 CS BT" A 26"x4½' high D.Fir stump bears N.46°W., 14.2 ft. scribed "SW DLC 41 CS BT" All new bearing trees were cut to high stumps shortly after renewal. Note - COMPASS DECLINATION 15½° All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown. Corner falls on a moderate Easterly Slope in a new clearcut unit approximately 100 feet North of a draw bearing NW.	
1	