

PRIMARY CORNER DESCRIPTION N. 1/16 Cor. for Secs. 17 & 18

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Bureau of Land Management Dependent Resurvey - Zirbel, Corbin and Roseberry - Special Instructions dated June 8, 1957 and June 15, 1958 - (DCSO records, Volume 29 Page 12317)

-----  
Set an iron post, 28" long 2½" dia. 24" in the ground, with brass cap marked:

N 1/16

S 18 | S 17

1957

from which

A Fir 7" dia. bears S.71¼°E., 62½ lks. dist., marked N 1/16 S17 BT.

A Fir 17" dia. bears N.13¼°W., 46 lks. dist. marked N 1/16 S18 BT.

Doug. Co. Surveyors Office - Vernon Tracy; Mike Darby; Jack Barnett - Jan/Feb. 1965 - C.S. File 53/47-5

-----  
Found - 1957 BLM brass cap and BTs as follows:

7" now 11" Fir S.71¼°E., 41.3 ft., scar healed over  
We do not open.

17" now 18" Fir snag N.13¼°W., 30.4 ft. scribe visible on partially healed over blaze. Snag is about 20 ft. high.

New BT - 9" Madrone N.23°W., 46.7 ft. mkd: N 1/16 S 18 CS BT  
This corner lies in N-S fence.

Fd. & used on BLM dependent resurvey by Wayne L. Rogers, Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Surveying Technician, under Group #1755 surveyed June/Oct. 1995 - (DCSO records Vol. 52 Page(s) 19900-1)

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2748, surveyed July 2014 - (DCSO records Vol. 58 Page 23174 & Plat 25-4 2015-1a&b)

-----  
The N 1/16 sec. cor. of secs. 17 and 18, monumented with an iron post, 2½" dia., firmly set, projecting 7" above ground, with brass cap (properly) mkd.

from which the remains of a BT mkd. by Zirpel, Roseberry, and Corbin in 1957-58

A fir, 29" dia., bears S.72¾°E., 41.6 ft., with a healed blaze. (Record, S.71¼°E.)

and new bearing trees

A fir, 4" dia., bears N.73½°E., 7.4 ft., mkd. X BT.

A fir, 5" dia., bears S.14¼°W., 9.4 ft., mkd. X BT.

Corner is located on the west side of a barbed wire fence extending N. and S.