

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7, 8, 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records, Volume 9 Page 3738)

Set post cor. of secs. 7, 8, 17 and 18, from which
A Fir 80" dia. bears N.80°W., 8 lks. dist.
A Fir 40" dia. bears N.63°E., 154 lks. dist.
A Fir 36" dia. bears S.2¼°W., 89 lks. dist.
A Laurel, 20" dia. bears S.60°E., 297 lks. dist.

A. Boyer, for: Mr. Crowell - Dec. 1941 - C.S. File 35/61

Find stump of 80" Fir, orig. BT, N.80°W., 8 lks.
Drove Fir post.
Renewed or remarked 40" Fir N.63°E., 154 lks.
New BTs:
Red Fir 18" dia. N.48°W., 38 ft.
A Fir 30" dia. S.70°W., 55 ft.
A Laurel 20" dia. S.55°E., 57½ ft.

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin
and Roseberry - Special Instructions dated July 8, 1957 and
July 15, 1958 (DCSO records, Volume 29 Page 12317-8)

Found - Point for the cor. of secs. 7, 8, 17 and 18,
perpetuated by an iron post, 36" long 1½" dia. protruding
18" above ground, & a weathered Fir stake, 2 ft. long 2"
square protruding 12" above the ground, scribed 7 8 17 18,
from which the remains of the orig. BTs:

A Stump hole, bears N.80°W., 8 lks. dist.
and trees marked by local surveyors:
A sawed fir stump 51" dia. bears N.63°45'E., 159½ lks.
dist. with lower end of healed blaze visible.
A Madrone 26" dia. bears S.60½°E., 92 lks. dist. with
rotted out blaze.
A sawed Fir stump 27" dia. bears S.70°W., 78½ lks. dist.
bark scribed W S BT.
A sawed Fir stump 21" dia. bears N.48°W., 57½ lks. dist.
bark scribed 5S R4W BT.

At the corner point, set an iron post 28" long 2½" dia. 25" in
the ground, with brass cap marked:

T25S R4W
S 7 | S 8
S 18 | S 17
1957

from which

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7, 8, 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 14" dia. bears N.80°E., 196 lks. dist. marked
T25S R4W S8 BT.
A Fir 60" dia. bears S.85¼°E., 349½ lks. dist. marked
T25S R4W S17 BT.
An Oak 9" dia. bears S.13¼°W., 137 lks. dist. marked
T25S R4W S18 BT.
A Fir 7" dia. bears N.36¼°W., 86 lks. dist. marked
T25S R4W S7 BT.
Corner of barbed and woven-wire fences extending N.5°W. and
East, bears N.65°E., 1½ lks. dist.
Reset Iron post and Fir stake alongside the iron post.

BLM Dependent resurvey by Joseph M. Mannix, Cadastral
Surveyor under Group No. 2748, surveyed July 2014 - (DCSO
records Vol. 58 Page 23174 & Plat 25-4 2015-1a&b)

The cor. of secs. 7, 8, 17, and 18, monumented with an iron
post, 2½" dia., firmly set, projecting 3" above ground,
(alongside of which is an iron pipe, 1½" dia., firmly set,
projecting 2 ft. above ground) with brass cap (properly) mkd.
from which the remains of BTs mkd. by Zirpel, Roseberry, and
Corbin in 1957-58
A fir stump, 38" dia., bears N.80°E., 129.4 ft., with a
healed blaze.
A fir, 70" dia., bears S.85¼°E., 230.7 ft., with a
healed blaze.
An oak, 13" dia., bears S.12½°W., a healed blaze. 90.4
ft. with a healed blaze. (Record, S.13¼°W.)
and a new bearing tree
A fir, 5" dia., bears N.81¼°E., 24.0 ft., mkd. X BT.
Corner is located S.65°W., 1 ft. from the remains of fences
extending N, S, and E.