

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sections 20 and 29

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - W. H. Byars, Contract #152 dated June 1871  
(DCSO records, Volume 9 Page 3756)

-----  
Set ¼ sec. post, from which  
    A Fir 48" dia. bears N.69°E., 5 lks. dist.  
    A Fir 40" dia. bears S.73°E., 24 lks. dist.

-----  
Wilford N. Haines, For: Mt. Baldy Lumber Co. Feb. 15, 1956  
M 2-41

-----  
Found stumps of 2 original BTs.  
Set 36" angle iron with brass cap inscribed: Survey Point -  
Wilford N. haines # 239.

-----  
Bureau of Land Management Dependent Resurvey - Zirpel, Corbin  
and Roseberry - Special Instructions dated July 1957 and  
July 1958 - (DCSO records, Volume 29 Page 12310)

-----  
Found - Haines angle iron.  
    A sawed fir stump 52" dia. bears N.69°E., 5 lks.  
        dist. to face, with a faint bark blaze; no  
        scribe marks visible. (Orig. BT)  
    A fir stump hole, fir down & rotted, approx. 40"  
        dia. bears S.73°E., 24 lks. dist. (Orig. BT)  
    A locally established bearing tree, a sawed fir  
        stump 25" dia. bears S.85°W., 40½ lks. dist.  
        with BT visible on opened blaze.  
At the corner point, set an iron post, 28" long 2½" dia. 26"  
in the ground, with brass cap marked: T25S R4W  
  ¼ S 20  
  S 29  
  1957 from which  
    A Fir 8" dia. bears N.20½°E., 58½ lks. dist. marked  
        ¼ S20 BT.  
    A Fir 22" dia. bears S.85¼°W., 139 lks. dist. marked  
        ¼ S29 BT.  
Deposit angle iron alongside iron post.  
Corner falls on W. edge of swamp, edge bears N. and S. and in  
a fence row with fences extending E. and W.

(Continued Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. Section 20 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Bureau of Land Management Dependent Resurvey - Jelley and Rogers, Group #1084 - Survey, Jan./June 1982 (DCSO records Volume 45 Page 17523-24)

-----  
Found - 1957 BLM brass cap  
Orig. BT, a sawed Fir stump 52" dia. bears N.69°E.,  
8 lks. dist., no marks visible. (Rec. 5 lks.)  
1957 BT, A sawed Fir stump 22" dia. bears S.85°W.,  
40½ lks. dist., with scribe mark BT visible on  
opened blaze.  
1957 BT, A root hole, bears S.85¼°W., 139 lks. dist.  
with an uprooted fir alongside, 22" dia., no  
marks visible.  
New BTs - A Fir 15" dia. bears N.75°W., 109 lks. dist. marked  
¼ S20 BT.  
An Ash, 23" dia. bears S.26°W., 21 lks. dist. marked  
¼ S29 BT.

Ken Hoffine, Lone Rock Timber Co. - 2/16/2007 - C.S. File  
65/60-12

-----  
Found - 1975 BLM brass cap with Haines T-iron alongside  
28" D.Fir bears N.75½°W. 72' (Rec N.75°W. 71.94 ft)  
23" Ash has been fell by beaver and in down and out  
of position.  
New - 17" D.Fir bears N.72½°E, 46.20 ft, we scribe ¼ S20  
BT and tag  
14" D.Fir bears N4¼°W, 28.9 ft, we scribe ¼ S20 BT  
and tag  
Note - Corner lies in fence lines at North end of large  
beaver pond