

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records, Volume 9 Page 3741)</p> <p>-----</p> <p>Set 1/4 sec. post, from which An Ash, 18" dia. bears N.53°W., 262 lks. dist. A W.oak 18" dia. bears N.50°E., 213 lks. dist.</p>
<p>Ben B. Irving, Dep. Co. Surveyor For: State of Oregon N.E. Richardson; Harvey Eppstein; Robt. Helliwell June, 1939 - C.S. File 37/204 - M 5 - 66</p> <p>-----</p> <p>Orig. BT now down and almost destroyed but part of the scribed "T" of the BT still vis. W.Oak 18" N.50°E., 213 lks. Drove a 1" x 3" channel iron 36" long 35" in the ground for the corner, from which Oak 8" dia. bears N.45°E., 81.5 ft. "1/4 S21 CS BT." Cedar 12" dia. bears N.86°35'W., 188.7 ft. "1/4 S20 CS BT."</p>
<p>Wilford N. Haines - For Baldy Lumber Company - Feb. 15, 1956 File Map M 2-14</p> <p>-----</p> <p>Found 1" x 3" channel iron and 2 BTs set by Co. Surveyor Set 36" angle iron with brass cap 4.73 ft. east on fence line inscribed Survey Point - Wilford N. Haines # 239.</p>
<p>Found OK, Larry Dolan, M 93-19, 10/82 and M 96-54 5/84</p>
<p>Ken Hoffine, Lone Rock Timber Co. - 2/16/2007 - C.S. File 65/60-12</p> <p>-----</p> <p>Found - 1" x 3" channel iron 0.2 feet below ground 26" cedar bears N.87 1/4°W., 188.9 ft (rec N.86°35'W., 188.7 ft) Healed face and tag 19" oak bears N.44 1/2°E., 80.7 ft (rec N.45°E., 81.5 ft) healed face and tag.</p> <p>Set - 5/8"x40" iron rod with yellow plastic cap marked Lone Rock Timber PLS 2291 bears S.5°51'W., 38.82 ft in fence line 5/8"x40" iron rod with yellow plastic cap marked Lone Rock Timber PLS 2291 bears N.26°27'W., 103.82 ft in fence line</p> <p>Note - Corner lies 0.2 ft. below ground in pasture. Fence line bears East approx. 10.7 ft.</p>