

PRIMARY CORNER DESCRIPTION Sec Cor for 27, 28, 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records, Volume 9 Page 3753)

Set post cor. of secs. 27, 28, 33 and 34, from which
A Laurel 15" dia. bears N.83°W., 21 lks. dist.
A Fir 15" dia. bears S.65°W., 26 lks. dist.
A Fir 30" dia. bears S.35°E., 28 lks. dist.
A Fir 8" dia. bears N.44°E., 18 lks. dist.

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin
and Roseberry - Special Instructions dated July 8, 1957 and
July 15, 1958 - (DCSO records, Volume 29 Page 12289)

The cor. of secs. 27, 28, 33 and 34, determined at record
distance from the original bearing trees as follows:
A Fir 14" dia. bears N.42½°E., 18 lks. dist. with
an opened blaze, no scribe marks visible. (Record
bearing N.44°E.)
A sawed Fir stump 47" dia. bears S.35°E., 28 lks. dist.
no scribe marks visible, stump sawed low.
A sawed Fir stump 26" dia. bears S.67°W., 26 lks. dist.
with an opened face, no scribe marks visible. (Rec.
bearing S.65°W.)
At point for corner, set an iron post, 28" long 2½" dia. 26"
in the ground, with brass cap marked: T25S R4W
S 28 | S 27
S 33 | S 34
1957 from which
A Cedar 15" dia. bears N.26½°E., 31 lks. dist. marked
T25S R4W S27 BT.
A Cedar 17" dia. bears S.74½°E., 43½ lks. dist. marked
T25S R4W S34 BT.
A Fir 18" dia. bears S.54°W., 82 lks. dist. marked
T25S R4W S33 BT.
A Cedar 12" dia. bears N.3¼°W., 100 lks. dist. marked
T25S R4W S28 BT.

Doug. Co. Surveyors Office - V. Tract; M. Darby; J. Barnett
January, 1965 - C.S. File 53/47-32

Found - 1957 BLM brass cap and BTs as follows:
15" now 16" Cedar stump N.26½°E., 20.5 ft. scribe
visible on entire face, "T25SR4W S27 BT".

(Continued Next page)

