

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. H. Byars, Contract #152 dated June 1871
(DCSO records, Volume 9 Page 3765)

Set 1/4 sec. post, from which
 A Fir 10" dia. bears N.40°E., 19 lks. dist.
 A Cedar 10" dia. bears S.58°W., 12 lks. dist.

James W. Byron, Deputy Co. Surveyor - For: Wilbur Lbr. Co.
November 1955 - C.S. File 47/44 and M 2-1

Corner renewed from original BTs:
 10" Cedar, S.38°W., 7.92 ft.
 12" Cedar, stump only left, scribed BT. Also found broken
 top of Cedar downhill (East) scribed 1/4 S.
Set 5" x 5" Cedar post at corner, from which
 18" R.Fir S.74°W., 47.5 ft. mkd. 1/4 S 34 C.S. BT.
 34" Cedar bears N.21°E., 22.0 ft. mkd. 1/4 S 27 C. S. BT.
BLM tag 100 ft. West on logging road.

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin
and Roseberry - Special Instructions dated July 8, 1957 and
July 15, 1958. (DCSO records, Volume 29 Page 12288-89)

The 1/4 sec. cor. of secs. 27 and 34, perpetuated with a cedar
stake 5" sq. in cross section, 5 ft. above ground, firmly set.
This corner was restored from the 2 orig. BTs by the County
Surveyor in 1955, one of which is still standing, as follows:

 A chopped cedar stump 12" dia. bears S.55 1/4°W., 12 lks.
 dist. with BT visible on opened blaze and 1/4 S
 visible on a portion of the tree lying alongside
 the stump.

Locally established bearing trees:

 A cedar 33" dia. bears N.18 1/4°E., 33 lks. dist. mkd. 1/4 S27
 BT. CS

 A Fir 15" dia. bears S.72°W., 41 lks. dist. mkd. 1/4 S34
 CS BT.

At the corner point, set an iron post, 28" long 2 1/2" dia. 26"
in the ground, with brass cap mkd: T25S R4W

1/4 S 27
 S 34

1957 from which

 A Cedar 19" dia. bears N.41°E., 47 lks. dist. marked
 1/4 S27 BT.

(Continued Next Page)

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir, 18" dia. bears S.39½°W., 48 lks. dist. marked
¼ S34 BT.
Deposit old corner material alongside iron post.

Found BLM 1957 Brass cap and 5 BTs. BLM Resurvey by Bishop &
Rogers, 1983 - (DCSO records, Volume 46 Page 17771)