TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias Description
Alias Description
Alias Description
Alias Description

Original - W.H. Byars, Contract #152 dated June 1871
(DCSO records, Volume 9 Page 3764)

Set ¼ sec. post, from which
A Cedar 8" dia. bears N.78°E., 23 lks. dist.
A Laurel 7" dia. bears N.10°W., 30 lks. dist.

James W. Byron, Deputy Co. Surveyor - For: Wilbur Lbr. Co.
November 1955 - C.S. File 47/44 and M 2 - 1

Corner reset from original BT found, an 8" Cedar, now 24" which we opened and found ¼ S scirbe - I rescribe ¼ S BT.
Set iron pipe with brass cap mkd: ¼ S 34|S35 T 25 S R 4 W,
Co. Surveyors Office, 1955.
Blazed and Rescribed:
14' Yewwood, N.10°30'E., 43.8 ft. mkd: ¼ S 35 C.S.BT.
12" Cedar N.52°40'W., 66 ft. mkd: ¼ S 34 C.S. BT.

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin and Roseberry - Special Instructions dated July 8, 1955 and July 15, 1956. (DCSO records, Volume 29 page 12277-78)

Found - 1955 County Brass cap.
Orig. BT, A split Cedar snag 23" dia. bears N.78°E., 23 lks. dist. with scribe marks ¼ S visible on open blaze; tree has be rescribed ¼ S35.
1955 BT, a Yew 13" dia. bears N.10°E., 67 lks. dist. mkd. ¼ S35 CS BT on an unhealed blaze.
1955 BT, A cedar 12" dia. bears N.53°W., 100 lks. dist. mkd. ¼ S34 CS BT. on an unhealed blaze.
At the corner point, set an ironpost, 28" long, 2½" dia. 26" in the ground with brass cap marked: T25S R4W
¼
S 34|S 35
1957 from which
A Fir 14" dia. bears S.74¼°E., 104 lks. dist. marked ¼ S35 BT.
Deposit County Surveyor's corner post alongside Iron Post.