

PRIMARY CORNER DESCRIPTION Sec. cor. for 25, 26, 35 & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, Deputy Surveyor, Contract #152 dated June 1871 - (DCSO records, Volume 9 Page 3760)

-----  
Set post to secs. 25, 26, 35 and 36, from which  
A Fir 40" dia. bears N.70°E., 30 lks. dist.  
A Cedar 6" dia. bears S.10°E., 29 lks. dist.  
A Cedar 6" dia. bears S.35°W., 16 lks. dist.  
A Cedar 6" dia. bears N.32°W., 28 lks. dist.

Ben B. Irving - Wit. R.L. Irving; R.A. Kent; W.A. Finley  
June, 1927 - C.S. 37/147

-----  
Identified this corner by means of all 4 orig. BTs. Located as recorded in the original notes. Two of the old BTs were standing and in good shape but have been fire killed. I set a 4" seasoned Yew wood post for the corner and replace the 2 BTs by a  
10" Cedar S.10°E., 42.6 ft.  
10" Cedar S.60°W., 19 ft.

James W. Byron, Deputy Co. Surveyor - For: Wilbur Lumber Co.  
November 1955 - C.S. File 47/44

Found both Cedar BTs as renewed by Irving. Reset 3" x 3" post alongside. Found scribed part of orig. 6" Cedar.  
Set brass cap mkd: 26 25 T25S R4W Co. Su. Office.  
35 36  
Blazed and Scribed:  
18" Cedar, N.31°30'W., 78.0 ft. mkd. S 26 T25 R 4 W.  
Rebark Scribe 48" R.Fir N.70°E., 19.8 ft. mkd. S 25  
C. S. B. T.

BLM Dependent Resurvey - Zirpel, Corbin, Roseberry - Special Instructions dated July 8, 1957 and July 15, 1958. (DCSO records, Volume 29 Page 12267-68)

-----  
Found - 1955 County brass cap.  
Orig. BT, A fir, 55" dia. bears N.70°E., 30 lks. rescribed S25 CS on bark by co. surveyor.  
Orig. BT, a fragmentry piece of cedar stump, bears S.37½°W., 16 lks. dist., mkd. T25S S35 BT. (Record bearing S.35°W.)  
A Cedar 18" dia. bears S.9¼°E., 65 lks., mkd. S36 CS on partially healed blaze. (Co. Surveyor)  
A Cedar 18" dia. bears S.59¼°W., 30½ lks. mkd. T25S S35 CS on partially healed blaze. (Co. Sur)

continued next page

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Cedar 15" dia. bears N.31¼°W., 119 lks. dist. mkd.  
T25S S26 R4W CS BT on open blaze. (Co. Surveyor)  
At the corner point  
Set an iron post, 28" long 2P" dia. 26" in the ground with  
brass cap marked:                   T25S R4W  
  S 26 | S 26  
  S 35 | S 36  
  1957                   from which:  
A Cedar 15" dia. bears N.35°45'E., 97 lks. mkd. T25S R4W  
S25 BT.  
A Fir 41" dia. bears S.56°E., 60 lks. mkd T25S R4W S36 BT.  
A Cedar 27" dia bears S.17¼°W. 113 lks mkd T25S R4W S35 BT  
A Cedar 15" dia bears N.10°W., 120 lks mkd T25S R4W S26 BT  
Reset the iron pipe alongside the iron post.  
Corner falls at a fence corner with fences extending E. & S.

Ken Hoffine - For: Lone Rock Timber Co. - 1/19/2012 - C.S.  
File 65/76-12

-----  
Condition Report only  
Found - 1957 BLM BC (properly mkd) 0.2 ft. above ground  
level, with County cap alongside which is badly  
bent to the south.  
35" Cedar Bears S.9¾°E., 40.1 ft. (Rec. S.9¼°E.,  
42.9 ft.) Healed Face and B.T. Tag  
32" Cedar Bears S.57¾°W., 19.3 ft. (Rec. S.59¼°W.,  
20.13 ft.) Healed Face and Tag  
35" Cedar Bears N.34¾°E., 64.1 ft. (Rec. N.35¾°E.,  
64.02 ft.) Healed Face and Tag  
29" Cedar Bears N.10½°W., 77.8 ft. (Rec. N.10°W.,  
79.2 ft.) Healed Face and Tag  
Lone Rock ran a random traverse conventional survey from the  
S¼ easterly to the SESC, then northerly to the E¼ corner of  
section 26, which we close with GPS. The purpose of survey is  
to blaze and paint true line between monuments for timber  
management purposes. We located the above monuments during  
the course of this survey.