

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - W. H. Byars, Contract #152 dated June 1871
(DCSO records, Volume 9 Page 3762)

Set 1/4 sec.post, from which
 A Cedar 8" dia. bears N.50°W., 15 lks. dist.
 A Fir 30" dia. bears S.10°E., 14 lks. dist.

Doug. Co. Surveyors Off. - James Byron; G.Welker; J.Fee
November 20, 1956 - C.S. File 47/133

Found - 42" Fir S.10°E., 9.24 ft., blown down, bark scribe
 visible.
 18" Cedar N.50°W., 9.9 ft., Cut out with power saw
 scribe visible.
Set brass cap mkd: County Surveyors Office, 1956 1/4 S 23|S24
 T 25 S R 4 W.
New Bts - 13" Cedar N.45°00'E., 29.5 ft. scribed 1/4 S 24 CS BT.
 20" Cedar S.50°45'W., 28.5 ft. scribed 1/4 S23 CS BT.

Bureau of Land Management Dependent Resurvey - Corbin; Zirpel
and Roseberry - Special Instructions dated July 8, 1957 and
July 15, 1958 - (DCSO records, Volume 29 Page 12272)

Found - 1957 County brass cap.
 An uprooted Fir stump, 36" dia. bears S.10°E., 14
 lks. dist. with scribe mark S visible on opened
 blaze. (Orig.)
 A Cedar 15" dia. bears N.50°W., 15 lks. dist. with
 illegible scribe marks visible on opened blaze.
 (original BT)
 A Cedar 17" dia. bears N.44 1/2°E., 45 lks. dist.
 marked 1/4 S24 CS BT. (1957)
 A Cedar 25" dia. bears S.49 1/2°W., 45 lks. dist. mkd.
 1/4 S23 CS BT. (1957)

At the corner point, set an ironpost, 28" long 2 1/2" dia. 26" in
the ground with brass cap mkd: T25S R4W

1/4
S 23|S 24

1957 from which
A Cedar 16" dia. bears N.68°45'E., 82 lks. dist. marked
1/4 S24 BT.

A Cedar 8" dia. bears S.81 1/2°W., 84 lks dist. marked
1/4 S23 BT.

Reset the iron pipe alongside the iron post.

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Bureau of Land Management Dependent Resurvey - Bishop and Rogers, Group #1161, Survey July-Sept. 1983 (DCSO records, Volume 46 Page 17763-64)

Found - 1957 Brass cap.
Orig. BT, a root hole, bears S.12¼°E., 17 lks. dist., with fir stump alongside, no marks visible. (Rec. S.10°E., 14 lks.)
Orig. BT, A cedar snag, 17" dia. bears N.45 3/4°W., 14 Lks. no marks visible on opened blaze. (Rec. N.50°W., 15 lks.)
Byron BT, a root hole bears N.44½°E., 45 lks. dist. with downed cedar alongside, 25" dia. with healed double blaze.
Byron BT, a Cedar 34" dia. bears S.49½°W., 45 lks. dist. with healed double blaze.
1957 BLM BT, a Cedar stump 16" dia. bears N.73°E., 70 lks. dist. no marks visible. (Record, N.68 3/4°E., 82 lks.)
1957 BT, A Cedar 16" dia. bears S.82½°W., 80 lks. dist. with healed blaze. (Record, 84 lks.)
New BT - A Fir 4" dia. bears N.68½°E., 33 lks. dist. mkd. X BT.

FD OK, K HOFFINE - 2/8/2007 - C.S. FILE 65/60-26