

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, Deputy Surveyor under Contract #152 dated June 3, 1871 (DCSO records Volume 9 Page 3761)

Set $\frac{1}{4}$ sec. post, from which
A Fir 16" dia. bears N.60°W., 8 lks. dist.
A Fir 15" dia. bears S.40°E., 4 lks. dist.

C.E. Roberts, For: J.S. Hunt - May 28, 1903 - Field Book 7 Page 8-9

Reset post and made new witness tree:
Fir 48" N.67°E., 22 lks.

Ben B. Irving - Wit. R.L. Irving; R.A. Kent; W.A. Finley June, 1927 - C.S. File 37/147

This corner is a 12" Fir tree with O.B.T.'s as described in the original notes except the Fir S.40°E., is 4 lks. dist. instead of 40 lks. Remarked.

Bureau of Land Management Dependent Resurvey - Zirpel; Corbin and Roseberry - Special Instructions dated July 8, 1957 to July 15, 1958. (DCSO records, Volume 29, Page 12268-9)

The $\frac{1}{4}$ sec. cor. of secs. 25 and 36, a rotted fir stump, 12" dia. marked on E. face by the county surveyor with illegible scribe marks visible on rotted blaze, from which the remains of the original bearing tree:

A fir stump 24" dia. bears N.60°W., 8 lks. dist., with no scribe marks visible on old rotted and burned blaze.

At the corner point: Set an iron post 28" long, 2 $\frac{1}{2}$ " dia. 26" in the ground, with brass cap marked:

T25S R4W
 $\frac{1}{4}$ $\frac{S}{S}$ $\frac{25}{36}$

1957 from which:

A Madrone 6" dia. bears N.51°W., 68 lks. dist. marked $\frac{1}{4}$ S 25 BT.

A Madrone 8" dia. bears S.73°E., 166 lks. dist. marked $\frac{1}{4}$ S 36 BT.

Deposit the fir stump alongside the iron post. Corner falls by a fence extending N and S on spur, sloping South.

continued next page

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 11/1/2004 - C.S. File 67/6-24

Found - BLM BC/IP on top of ground near fence corner.
(Properly mkd.) 1957
19" Madrone, fully healed single blaze w/tag bears
N.51°W., 44.9 ft. (1957 BLM)
Rotted remnants of 15" Fir (OBT - S.40°E., 4 lks)
lies between rounded fence cor. & B. Cap.
New - Used position of 19" Madrone to re-establish corner.
3" BC on 2½" IP.
14" DBH W.Oak scribed "¼ S25 CS BT" on a double
blaze bears N.54°E., 77.0 ft.
11" DBH I.Cedar scribed "¼ S36 CS BT" on a double
blaze bears S.12°W., 180.5 ft.
16" DBH D.Fir scribed "¼ S36 CS BT" on a double
blazed bears S.54°W., 46.4 ft.
Note - Monument is on East edge of cat road on crest of
North-South running spur ridge. Quadrant South &
East of corner position was logged recently.