


PRIMARY CORNER DESCRIPTION Center S 1/16 Cor Sec 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin and Roseberry - Special Instructions dated July 8, 1957 and July 15, 1958 (DCSO records, Volume 29 Page 12321)

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:



1958 from which
A Fir 13" dia. bears N.31½°E., 43½ lks. dist., marked CS 1/16 S13 BT.
A Cedar 17" dia. bears S.35°W., 150½ lks. dist. marked CS 1/16 S13 BT.

Doug. Co. Surveyors Office - V. Tracy; M. Darby; J. Barnett
Jan/Feb. 1965 - C.S. File 53/47-6

Found - 1958 BLM brass cap.
13" D.Fir N.31½°E., 28.7 ft., now snag, shows scribe on pitched over face.
12" now 21" Cedar S.35°W., 99.3 ft. top broken off approx. 20 ft. above ground, still alive.
New BT - 14" I.Cedar N.89°W., 137.7 ft. mkd: CS 1/16 S13 CSBT
This corner lies 3.5 ft. East of N-S fence.