

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, Deputy Surveyor, Contract #152
dated June 3rd. 1871

Set ¼ Sec. Post, from which
 A Fir, 16" dia. bears N.34°W., 100 lks. dist.
 A Fir 18" dia. bears N.66°E., 58 lks. dist.

Stephen H. Ford - April, 1955 - C.S. File 41/376, M 28-41

Set - 5/8" Iron pin, from which
 Found a 34" Fir, Orig. BT, N.66°E., 37.98 ft.
 Found a 28" Fir, Orig. BT, N.34°W., 66.0 ft.

Doug. Co. Surveyors Office - Vernon Tracy; Jack Heritage;
V. Perron - August 20, 1968 - C.S. File 49/124-98

Found - Orig. 16" now 34" Fir stump N.34°W., 66.0 ft. scribe
 visible, we open higher & find scribe & reverse
 No trace of oBT to NE or the 5/8" I.R. as recorded
 by Ford or NE OBT.

Set - Brass cap at cor. mkd: County Surveyors T25S R5W
 (Set 6' steel fence Office 1968 ¼ S28|S27
 alongside B.C.)

New BT - 20" D.Fir S.74°E., 112.9 ft. mkd. ¼ S27 CS BT.
 Bearing tree is on top of cut bank of log land-
 ing, E. of corner.

No other trees available.

Set 6 ft steel fence post along side brass cap.

Corner lies on very steep W. slope, clear cut all around
except for seed trees to East.

Fd. OK - Daniel Baker - 10/05/95 - M 119 -74

Found OK by K. Hoffine, Dec, 2001 - M137-29