

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, contract #31 dated April, 1853

Set ¼ Sec. post, from which
 A W.Oak 12" dia. bears S.29°E., 32 lks. dist.
 A Y.Oak 16" dia. bears S.47°W., 61 lks. dist.

J.W. Cole, Deputy Co. Surveyor - L.H. Smick & P.D. Wolford
November 1920 - Vol. 3 Pg. 82; F.B. 49 Pg. 31; M6-21

Established this corner from the old BTs which are standing
but dead & rotten. Scribe marks visible on tree SE. Trees
check for direction & distance.
Set a 5" x 5" x 48" Oak stake from which new trees:
 A Fir 16" dia. S.59°30'E., 20.5 ft. mkd. C.S.B.T.
 A Fir 16" dia. S.71°W., 51.5 ft. mkd. C.S.B.T.

James W. Byron, Deputy Co. Surveyor; Milo Godfrey; Clete
Putnam - May & June 1960 - C.S. File 49/124-64

Found - No original BTs.
 Cole's S.71°W., 51.5 ft., new 24" stump, shows good
 bark scribing "BT".
 The SE BT in logging road not found.
Set - Brass cap at cor. mkd. County Surveyors Office 1960
 ¼ S22|S23 T25S R5W
New BTs - 6" R.Fir bears N.36°E., 13.8 ft. scribed ¼ S23 CSBT.
 5" R.Fir bears N.75°W., 34.4 ft. scribed ¼ S22 CSBT.
Scribing on each BT on one face only. ¼ Cor. bears N.70°W from
fence corner, fences running North and E-W.

Douglas County Surveyors Office - ED Monrean & Randall Smith
- 6/30/97 - C.S. 64/75-19

Mon. Fd.- 2½" Brass cap on a 1½" O.D. iron pipe protrudes 14"
 above ground.
Bt's Fd.- 16" now 24" dia. 2½' high rotted D.Fir stump, with
 flat bark and illegible bark scribing, bears
 S.71°W., 51.5' (agrees with rec.) 1920
 5" now 18" dia. D.Fir, with a fully healed single
 blaze, bears N.75°W., 34.4' (agrees with rec.)
 1960
NE BT from 1960 not found.

(Cont. Next Page)

