

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18 & 19 of T25-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - James E. Freeman, Deputy Surveyor, Contract #1 dated May 28, 1851 (DCSO records, Volume 9 Page 3730)

-----

Set post at cor. to Secs. 13, 18, 19 and 24, from which  
 A B.Oak 14" dia. bears N.7¾°W., 925 lks. dist.  
 A B.Oak 12" dia. bears N.3½°E., 926 lks. dist.  
 Made trench as per instructions.

BLM dependent Resurvey, Irving Zirpel, Jr. Lynn Roseberry; hrold Corbin - Special Instructions dated July 8, 1957 and July 15, 1958 (DCSO records, Volume 29 Pg 12266)

-----

The cor. of secs. 13, 18, 19 and 24, determined at record bearing & distance from the remaining original bearing tree in field,

An uprooted & decayed B.Oak 25" dia. bears N.7°45'W., 925 lks. dist. I opened a badly decayed blaze & found 5W T25S S13 on over growth.

At the corner point, Set an I.P. 28" long 2½" dia. 27" below the surface of the ground, with brass cap marked:

T25S  
 R5W|R4W  
S 13|S 18  
 S 24|S 19  
 1957

from which

An Ash 12" dia. bears N.6½°E., 427 lks. dist. mkd. T25S R4W S 18 BT.

An Ash 11" dia. bears S.37°E., 591 lks. dist. mkd. T25S R4W S 19 BT.

An Ash 7" dia. bears S.22°W., 523 lks. dist. mkd. T25S R5W S 24 BT.

An Ash 10" dia. bears N.67¼°W., 313 lks. dist. mkd. T25S R5W S13 BT.

Victor McLind, for: Bob Wiley - Oct. 18, 1971 - M 43-79

-----

Did not find 1957 BLM brass cap.  
 Reset corner from BTs as follows:  
 12" Ash beas N.6½°E., 281.8 ft.  
 11" Ash bears S.37°E., 390.1 ft.  
 7" Ash bears S.22°W., 345.2 ft.  
 10" Ash bears N.67½°W., 206.6 ft.  
 Set 5/8" Iron Rod at corner.

Cont. Next page

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24 of T25-5

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Douglas Co. Surveyors Office - Randall Smith & Stephen  
Flause - Aug. 6, 1997 - C.S. 64/75-34

-----  
Mon. Fd.- 5/8" I.R. bent flush with ground. (1971)  
Found 3" dia. BLM brass cap iron pipe 23" below  
ground. 1957

(Note: BLM Bc/Ip not found by 1971 renewal)

Bt's Fd.- 10" now 19" dia. Ash, with a fully healed single  
blaze, bears N.67½°W., 206.6' (agrees with  
rec.) 1957 BLM.

7" now 9" dia. Ash, with a fully healed single  
blaze, bears S.22°W., 345.2' (agrees with  
rec.)

11" now 18" dia. Ash, with a fully healed single  
blaze, bears S.37°E., 390.1' (agrees with  
rec.)

12" now 20" dia. Ash, with a partially healed  
single blaze, scribing visible "5S 4W", bears  
N.6½°E., 281.8' (agrees with rec.) 1957 BLM

Mon. Set- Plumb position of 5/8" I.R. is referenced I.R.  
measures 29" long is straightened and reset  
at referenced position 10" below ground.

I.R. bears west .6' from BLM Bc/Ip.

Found OK by D.C.S.O. April 2003 - See map M137-62