

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 056030

PRIMARY CORNER DESCRIPTION SW Cor. Hurst DLC #56

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Original - Addison R. Flint, Contract #28 dated April, 1854

Set post from which

A W.Oak 20" dia. bears N.16°W., 175 lks. dist.

A W.Oak 18" dia. bears N.21°W., 173 lks. dist.

F.C. Frear; Ed Richards; Henry; August 10, 1917
Field Book 43 Page 2-3

Found W.O. N.16°W., 115.5 ft. Did not cut out.

Found W.O, N.21°W., 114.2 ft., stump, rotted.

Marked a 40" W.Oak "Cl 56 C.S.B.T" bears N.57¼°E., 81.5 ft.

Set 3/4" x 30" Iron bar for corner.

H. Crowder, Transitman, Co. Engineers Office - May 18, 1951
~~(Source of this corner report not found, 8/91 V.L.)~~ C.S. File
44/47-6

New bearing tree scribed 10" Y.Oak bears N.38°E., 31.7 ft.

DCSO - No trace of tree mentioned here found - Older trees
still there. Do not believe this was cor. renewed. C.S. 49/123
(Crowder Corner)

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy; Mike
Stone - July 19, 1962 - C.S. File 49/123-8

Found - ¾" Rod at corner & W.Oak now 46", N.16°W., 115.5 ft.
Had been opened previously, but not deep enough
chopped deeper & exposed old scribing on old
face. "R" legible. (Orig. BT.)

Remains of rotted Oak stump N.21°W., 114.2 ft. Too
far gone to find any markings. (Orig. BT)

W.Oak now 42" N.57¼°E., 81.5 ft. shows good axe scar
(No trace of tree reportedly mkd. in 1951, 10" Y.Oak N.38°E.,
31.7 ft.)

Set brass cap for cor. alongside Rod mkd: County Surveyor's
Office, 1962 T25S R6W S.W. D.L.C. 56 L".

New BTs - 15" W.Oak S.30°W., 19.3 ft. mkd. SW DLC 56 CS BT".

7" W.Oak N.73°E., 24.8 ft. mkd. SW DLC 56 CS BT.

Fence corner, fences N. S. & E. bears N.56°W., 11.5 ft.

Fd. OK by K.Degroot, May 1999 - M132-1