

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records, Volume 9 Page 3842)

Set 1/4 sec. post, from which
 A Y.Oak 12" dia. bears S.67°W., 302 lks. dist.
 A Y.Oak 20" dia. bears N.53½°W., 324 lks. dist.

Milo E. Godfrey, Dep. Co. Surveyor - Vernon Tracy; Mike Stone
July 19, 1963 - C.S. File 49/123-86

Found - 62" B.Oak N.53½°W., 213.8 ft. Cut open and found
 good scribing "1/4 S".
 42" B.Oak S.67°W., 199.3 ft. Scar visible on bark,
 didn't open.

Set 3/4" Iron reinforcing rod, 12" below ground surface. Corner
position falls in prune orchard.

Set WITNESS CORNER 30 ft. W. of 1/4 corner, with
 brass cap mkd: County Surveyors T25S R6W WC 1/4 S19
 Office 1963 30 ft. East S30
 to corner.

Rescribe -SW BT, 42" B.Oak S.63½°W., 172.4 ft. (from Wit.
Cor.) mkd: "W.C. 1/4 S30 CS BT".

New BT - 17" B.Oak N.65°W., 229.2 ft. mkd: WC 1/4 S19 CS BT.
Witness Corner lies 2 ft. East of N. & S. fence line.

C. Sweeden, surveyed for Sandi Henry, April 1998 - M 128-55

Condition report only

Found - 3/4" I.R. down 12" per DCSO corner record. Prune
orchard no longer in existence. Witness post
found bent over to ground. No fence.

62" B.Oak BT, N.53°30'W., 213.8 ft. w/tag, burn scar.

48" B.Oak BT, S.67°W., 199.3 ft. w/tag.

18" B.Oak BT, N.65°W., 229.2 ft. w/tag, scar.