

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4 of T26-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to secs. 33, 34, 3 & 4, from which
A W.Oak 18" dia. bears S.61°W., 21 lks.
A Y.Oak 14" dia. bears S.9°E., 82 lks.
A Y.Oak 14" dia. bears N.79°W., 127 lks.
A Y.Oak 20" dia. bears N.48°W., 93 lks.

H.L. Eppstein, Co. Surveyor - Witnesses: T.F. Powers; B.A. Lane - Sept. 9, 1930 - C.S. File 14/61

Set corner from old Oak BT in fair condition. Scribe marks plain. Set 3 x 3 x 36" post & mkd. following new BTs:
B.Oak 24" dia. S.64½°W., 7½ ft.
Fir 20" dia. N.19°E., 22.4 ft.
Fir 14" dia. S.12°E., 9.0 ft.
Fir 20" dia. N.56½°W., 25 ft.

Milo E. Godfrey's Crew, Vernon R. Tracy; Mike Stone
February 1963 - C.S. file 49/123-74

Found - Following BTs as recorded by H.L. Eppstein in 1930:
24" B.Oak S.64½°W., 7.5 ft. down rotting, no scribing left.
24" Fir stump N.19°E., 22.4 ft. shows good scar.
20" Fir stump S.12°E., 9.0 ft opened & found scribe visible.
30" Fir N.56½°W., 25.0 ft. showing good scar.
No trace of original BTs.
Set - Brass cap at cor. mkd. County Surveyors Office 1963
T25S R6W S 33 | S 34
T26S R6W S 4 | S 3
New BTs - 14" D.Fir bears S.85°W., 15.6 ft. mkd. T26S R6W S4 CS BT.
7" D.Fir bears N.46°E., 64.5 ft. mkd. S34 CS BT.
8" W.Oak bears S.35°E., 39.3 ft. mkd. T26S R6W S3 CS BT.

Doug. Co. Surveyors Office - Gary Langlitz; Pete Earle
May 6, 1974 - C.S. 56/51-7

Found - Brass cap & bearing trees as noted in 1963 report. This corner is now located at the toe of a slide area. The brass cap & all bearing trees except two have been subjected to movement in the slide. Measurements from the two undisturbed BTs:

continued next page
TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. 33 & 34; 3 & 4 of T26-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 7" now 8" D.Fir bearing N.46°E. 64.5 ft with scribing "S34 CS BT" visible.

An 8" now 10" W.Oak bearing S.35°E. 39.3 ft well healed are in agreement with each other & indicate the brass cap has moved approx. 4 ft. downhill. Based on the measurements from the two undisturbed BTs as noted previously, we remove the brass cap & reset it at a witness corner 100 ft. east of the true corner.

We remark the brass cap to read as follows:

County Surveyor's T26S
Office Witness Corner
1974 S33 | S34 R
 S 4 | S 3 6 W
 100 ft. west to cor.
 T26S
 1974 1963

We mark the following BTs for Witness Corner:

18" D.Fir bears S.83°W., 19.2 ft. scribed "WC T26S R6W S3 CS BT."

7" W.Oak bears N.52°E., 26.7 ft. scribed "WC T25S R6W S34 CS BT".

10" W.Oak bears S.79½°E., 32.8 ft. scribed "WC S3 CS BT."

15" Madrone bears S.15½°W., 82.4 ft. scribed "WC T26S R6W S3 CS BT".

This witness corner lies approx. 30 ft. south of a dirt road Declination 20° East.

Found OK May 1991, M 113 - 11
Found OK, April 1994 by Pieske - M 118-80.
Found Ok, May 1994 by K. DeGroot - M 119-30

DCS0-GIS Corner visitation - 7/6/2004 - Typed: 1/27/2011 -
C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - OK