

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----

Set ¼ Sec. post, from which  
A Laurel 16" dia. bears S.11°E., 27 lks. dist.  
A Y.Oak 12" dia. bears S.83°W., 46 lks. dist.

G.G. Stewart, For: J.A. & Fay Leatherwood, March 22, 1922  
C.S. File 2/14 and Volume 3 Page 112  
-----

Reset corner from Laurel, O.B.T. badly rotted. Other BT gone.  
Set rock for corner and marked:  
6" Fir N.51°W., 4.0 ft.  
10" Fir S.10°E., 12.0 ft.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracey; M Stone  
November, 1962 - C.S. File 49/123-45  
-----

Found - Sandstone rock, 6"x8"x9", with "X" cut in top.  
Laurel snag S.11°E., 17.8 ft. snag still standing  
but dead & badly rotted, entire north side  
gone.  
Uprooted & badly burned Firs, N.51°W., 4 ft. and  
S.10°E., 12 ft. No markings found on either.  
No trace found of orig. SW Oak.  
Set brass cap alongside rock, mkd: County Surveyors Office  
1962 T25S R6W ¼ S4|S3  
New BTs - 6" D.Fir N.25°W., 15.7 ft. mkd. ¼ S4 CS BT.  
9" D.Fir N.26°E., 15.7 ft. mkd. ¼ S3 CS BT.  
Cor. lies on E. slope approx. 70 ft. West of small stream  
flowing Southeast.

Found & Used, BLM Dependent Resurvey, 1972 - Fd. BC and 5 BTs.  
(DCSO records, Volume 36, Pages 15004-05)

Found OK June 1994 by K.DeGroot - M119-34.