

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, Contract #73 dated June 8, 1857 (DCSO records, Vol. 9 Pg. 3883)

Set ¼ sec. and Meander post, right bank Umpqua River, from which

A Fir 48" dia., bears N.5°W., 75 lks.

A Fir 48" dia., bears N.35°E., 89 lks.

J. W. Cole, Co. Surveyor - Wit: Geo. A. Streese; Ed Mosher; Dec. 18-22, 1923 Vol. 3 Pg. 175; C.S. File 2/25B; Field Book 52; and "old" corner book, Page 57.

I made a mound of rock 49.3 ft. North of 1/4 cor. as 1/4 cor. came in river. Corner was renewed from the old BTs, both of which were standing, but no marks were visible.

Marked new trees:

A Myrtle 10" S.69°00'W., 13.2 ft. mkd. W.C. CS BT.

A Myrtle 10" S.75°30'E., 23.3 ft. mkd. W.C. CS BT.

Doug. County Surveyors Office - Milo Godfrey, Deputy - Vernon Tracy; Clete Putnam - Dec. 1961 - C.S. File 49/76-15

Found - Rock mound set by Cole in 1923.

Myrtle now 24" S.69°W., not N.69°W., 13.2 ft., chopped open & found good scribing "WC CS".

Clump of small Myrtles bears S.75½°E., 23.3 ft., stooled out from larger myrtle which once stood there.

Note: The stumps of both orig. Fir BTs to the ¼ cor. are still in existence, although badly rotted.

Set Brass cap at cor. mkd: County Surveyor's Office, 1961

W. C. ¼ S7|S8 49.3 ft. S. to ¼ cor.

New BTs - 14" D.Fir N.69°W., 16.2 ft. mkd: W.C. ¼ S7 CS BT.

9" Myrtle N.87½°E., 45.7 ft. mkd: W.C. ¼ S8 CS BT.

Fd. Brass cap, Dec. 1992, M. Heimbürger, M 112-64

Fd. Brass cap, Sept. 15, 1993, M. Heimbürger, M 117-59

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flaese - 2/18/98 - C.S. File 64/79-31

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 9" above ground. (WC)1961

(Cont. next page)

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

48" now 48" dia. 3 ft. high D.Fir stump we open blaze and find rotted blaze with a lower axe mark and scribing "T" record bearing to orig. corner "N.5°W., 49.5 ft" bearing to wit. corner N.65°W., 6.0 ft.

48" now 36" dia. badly rotted 6 ft. high stump. No blazing or scribing visible. Record bearing to orig. corner "N.35°E., 58.7 ft" bearing to Wit. corner N.79°E., 27.0 ft. (OBT?)

BEARINGS TAKEN FROM WIT. CORNER ON THE FOLLOWING BTs.

10" now 29" dia. Myrtle with a large previously opened unhealed blaze, scribing visible "C" bears S.73½°W., 14.5 ft. to center of rootcrown (Rec. S.69°W., 13.2 ft., dist good to blaze) We single blaze 5 ft. high and scribe "CS BT".1923

1923 SE BT now gone, clump of young Myrtles near record "S.75½°E., 23.3 ft"

14" now 25" dia. D.Fir with a fully healed double blaze bears N.69°W., 16.2 ft. (Agrees with rec.) 1961

9" now 11" dia. Myrtle with a partially healed double blaze, illegible scribing visible, bears N.87½°E., 45.7 ft. (Agrees with rec.) 1961

New BT - 6" dia., D.Fir, double blazed and scribed "¼ S7 CS BT" bears N.26½°W., 18.6 ft.

Note - Corner lies approx. 70 ft. south of paved road center line on high bank of North Umpqua river.

Fd. ok by K. DeGroot, 3/2001 - M132-79