

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 16 and 17

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Wm. P. Heydon, under Contract #656 dated May 21, 1896 (DCSO records, Volume 9 Page 3914)

-----  
Set a Fir post, 3 ft. long, 4" sq. 24" in the ground for 1/4 sec. cor. marked 1/4 S on W face, from which  
A Fir 20" dia., bears S.46°E., 64 lks. dist.,  
mkd. 1/4 S BT.  
A Fir 10" dia., bears S.38°W., 46 lks. dist.,  
mkd. 1/4 SBT.

Claude Kerr, November 1953 - C.S. File 41/228

-----  
Found both original BTs.  
A 46" Fir bearing S.46°E., 42.2 ft.  
24" Fir bearing S.38°W., 30.4 ft.  
I set a 3" x 3" x 4 ft. Fir post for the 1/4 corner.

A.R. Evans, For: E.L. Branton - June 1954 - C.S. File 41/313

-----  
Found one O.B.T., a 24" Fir N.38°W., 46 lks.  
Set 4" x 4" Fir stake.

Doug. County Surveyors Office - Vernon Tracy; V. Perron;  
and Don Collins, BLM - May 13, 1970 - C.S. File 54/10-16

-----  
Found - Orig. 20" now 40" Fir stump S.46°E., 42.2 ft. find probable axe marks on bark.  
Orig. 10" now 21" Fir alive, S.38°W., 30.4 ft. prev. opened & shows "1/4".  
Set Brass cap at cor. mkd: County Surveyor's T 25 S R 7W  
Office, 1970 1/4 S 17|S 16  
New BTs - 14" D.Fir N.60 1/2°W., 13.0 ft. mkd. "1/4 S17 CS BT".  
12" D.Fir N.70°W., 10.6 ft. mkd. "1/4 S17 CS BT".  
From corner as set by us, find small squared post with hub tack in top, bearing N.38°E., 4.0 ft. This corner lies on steep NE slope approx. 75.0 ft. south of 5.0' creek, course easterly.

Found OK, Greg Lang, October, 1989, M 109-3