

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, Contract #73 dated
June 8, 1857 (DCSO records, Vol. 9 Page 3882)

Set ¼ sec. post, from which
 A Fir 24" dia., bears N.2°W., 36 lks.
 A Fir 18" dia., bears S.2°E., 16 lks.

Bert Udell, Engineer #2301, December 15, 1948; C.S. 40/174

Original BTs:
 24" Fir N.2°W., 36 lks., tree standing, ¼ S mkd. on bark
 scar does not show.
 18" Fir S.2°E., 16 lks., tree blown down, chopped out BT.
New BT - 30" Fir S.41°W., 18.5 ft.
Set Post at corner.

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage;
Vince Perron; and Jim Rabe of BLM - March 28, 1969 - C.S.
File 54/10-12

Found - Orig. 24" now 48" Fir N.2°W., 23.8 ft. now only
 shattered stump "¼S". Bark scribe visible.
 Orig. 18" now 24" Fir S.2°E., 10.6 ft. turned out.
 Opened in 1948 by Udell & "BT" scribe exposed.
 30" Fir S.41°W., 18.5 ft., down, blaze decayed. No
 positive scribe marks found. Udell's BT.
Set 1" I.P. with brass cap mkd: County Surveyor T25S ¼ S5|S4
 R7W, Office, 1969
New BTs - 8" W.Fir N.60½°W., 42.0 ft. mkd. "¼ S5 CS BT".
 12" W.Fir S.19°E., 21.0 ft. mkd. "¼ S4 CS BT".
Corner lies on a steep SW slope.

Fd & used on BLM dependent resurvey by Bryan S. Seibold &
Wayne Rogers, Cadastral Surveyors, under Group #1862,
surveyed Sept.-Dec. 1997 - (DCSO record Vol. 53 Page(s) 20305)

Ronald Rice - For: Roseburg Resources Co - Jan 2011 - M162-1

Found - 1969 Douglas County brass cap
 48" D.Fir stump bears N.2°W., 23.8' - bark scribing
 visible.
 19" W.Fir bears S.19°E., 20.8' - healed face
 21" W.Fir bears N.60¾°W., 42.2' - healed face
New BT - 32" I.Cedar bears N.78°E., 19.4' - blazed, scribed
 "¼ S4 BT"