

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, Contract #63 dated
March 22, 1856 (DCSO records, Vol. 9 Page 3867)

Set Post corner of secs. 21, 22, 27 and 28, from which
A Fir 12" dia., bears S.46°W., 23 lks.
A Fir 15" dia., bears S.22°E., 33 lks.
A Fir 20" dia., bears N.52°W., 30 lks.
A Fir 12" dia., bears N.20°E., 35 lks.

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage;
V. Perron; and Chet Sorenson, BLM. - April 30, 1968
C.S. File 54/10-11

Found - Orig. 12" now 16" Fir, alive, N.20°E., 16.5 ft.
(Rec. 23.1 ft. shows scar.
Orig. 20" now 36" Fir, alive, N.52°W., 19.8 ft.
shows bark scribe.
Orig. 15" now 24" Fir, down, S.22°E., 21.8 ft.,
scribe visible in break.
Orig. 12" now 16" Fir, alive, S.46°W., 15.4 ft.
opened and shows "BT".

Set Brass cap at cor. mkd: County Surveyors T 25 S R 7 W
Office S 21 | S 22
1968 S 28 | S 27

New BT - 11" D.Fir S.21°E., 24.8 ft. mkd. T25S R7W S27 CSBT
Remarked: Orig. 16" D.Fir N.20°E., 16.5 ft. mkd. "T25S R7W
S22 CS BT."
Orig. 16" D.Fir S.46°W., 15.4 ft. mkd. "T25S R7W
S28 CS BT."

This corner lies on moderate S. slope at NE corner of old
cut-off unit.

BLM resurvey by Roseberry, 1967-68 found Brass cap and
five BTs. (DCSO records, Vol. 36 Page 14961)

Doug. County Surveyors Office - Stephen Flause; Terrie
Franssen - Jan. 18, 1991 - C.S. File 64/13-2

Found - 1968 DCSO brass cap, properly mkd. on a 1 3/8" O.D.
I.P., firmly set & protruding 10" above ground.
19" Fir (DBH) 40 ft. tall rotted Fir snag with
scribe marks "T25SR7WS28CSBT" visible on open
upper and lower blazes, S.46°W., 15.2 ft. (Orig)
15" Fir now a shattered, fallen and rotted stump
with no visible scribe marks, bears S.20½°E.,

(Cont. Next Page)

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21, 22, 27 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

21.8 ft. (Rec. S.22°E., 21.8 ft.) Orig. BT.
20" Fir now a 37" Fir (DBH) with a healed lower blaze & the bark scribing "T25SR7WS21" visible above, bears N.52°W., 21.0 ft. (Rec. N.52°W. 19.8 ft.) Appears to be a face measurement.
12" Fir now a 19" (DBH) with a fully healed double blaze bears N.20°E., 16.5 ft. (Rec. N.20°E., 23.1 ft.) Orig. BT.
11" D.Fir now an 11" DBH 10 ft. tall snag, with healed single blaze, bears S.21°W., 24.8 ft.
New BTs - 21" (DBH) Cedar with 2 square blaze scars (tree is tagged but otherwise unrecorded) bears N.81½°E., 17.5 ft.
4" (DBH) D.Fir double blazed & scribed "X BT" bears S.58°E., 19.3 ft.
Cor. located approx. 400 ft. East from logging road turnout. Cor. is in old growth timber just East of North-South cutting line.

Fd. Ok by David Edwards, July 2001 - M 138-39

Found OK by D. Edwards, Feb. 2004 - M144-13