

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 & 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, Contract #73 dated June 8, 1857 (DCSO records, Vol. 9 Page 3875)

Set post cor. secs. 10, 11, 14 and 15, from which
A Fir 24" dia., bears S.72°E., 18 lks. dist.
A Fir 12" dia., bears N.30°E., 23 lks. dist.
A Fir 12" dia., bears N.80°W., 39 lks. dist.
A Fir 24" dia., bears S.58°W., 57 lks. dist.

Doug. County Surveyors Office - James Byron, Deputy; Milo Godfrey; S. bilow - Nov. 1957-May 1958 - C.S. File 49/76-6

Found - 3" x 3" scribed sq. post at corner. This corner renewed about 15 years ago by County Surveyor, Boyer.

I find all four BTs as renewed:
Cedar bears N.61°E., 56.1 ft. scribe & face grown over.
I do not open.
Cedar bears S.15°W., 29.5 ft. some scribing visible.
Cedar bears N.70°W., 27.6 ft. some scribing visible.
Cedar bears S.43°E., 44.8 ft. scribing visible "14 25S R7W CS BT".

Set Brass cap at cor. and alongside 3" x 3" sq. post.
Cap marked: $\begin{array}{c} S\ 10\ | \ S\ 11 \\ S\ 15\ | \ S\ 14 \end{array}$ T25S R7W County Surveyors Office 1958

I find no original BTs.

BLM resurvey by Irving Zirpel under Group #411. Survey, 1958 (DCSO records, Volume 29 Pages 12392-93)

Sec. Cor. monumented with an I.P. 1" dia., 10" above ground, firmly set, with 1957 County brass cap and recorded as a perpetuation of the original cor. which was renewed by County Surveyor Boyer, in 1944, but not recorded. I find no evidence of the original bearing trees but find the wooden stake set by Boyer, which is 4x4 ins. cross section, firmly set, 2 ft. above ground, mkd. S10 on NW., S11 on NE.; S14 on SE.; and S15 on SW. faces. I also find the bearing trees mkd. by Boyer in 1944. I accept this cor. as the best available evidence of the original.

From the County Surveyor's 1944 bearing trees:
A Cedar 22" dia. bears N.61°E., 85 lks. with a partially healed blaze.
A Cedar 25" dia., bears S.43¼°W., 68 lks. with scribe marks 14 25S R7W CS BT visible on an unhealed blaze

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A Cedar 20" dia., bears S.15¾°W., 45 lks. dist., with scribe marks 25 7 S BT visible on an unhealed blaze.
A Cedar 20" dia., bears N.69°W., 41½ lks. dist. with scribe marks 10 25 7W S BT visible on an unhealed blaze.
At the corner point
Set a Iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd:
T25S R7W
S 10 | S 11
S 15 | S 14
1958
Deposit local corner material alongside iron post.

Found OK, March 1994 by R.Dolan - M118-74
Found OK, Feb. 1996 by K. DeGroot - M 124-3
Fd. as per M165-11 by C Sweeden, 10/2015 - M170-14