

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, Contract #73 dated June 8, 1857 (DCSO records, Vol. 9 Page 3876)

Marked a Laurel, 6" dia., for ¼ sec. post, from which
A Laurel 6" dia., bears N.30°E., 18 lks.
An Oak 15" dia., bears West, 13 lks.

BLM survey by Irving Zirpel, under Group #411 dated August 1958. Survey, Sept./Oct. 1958 (DCSO records, Vol. 29 Pages 12393-94)

The ¼ cor. marked with the original madrone corner tree, 17" dia., no marks visible, from which the original bearing trees as follows:

A Madrone 15" dia., bears N.30°W., 18 lks. dist., no mrks visible.

A fallen and rotted Oak 13" dia., the stump hole of which bears W., 13 lks. dist., I open a healed blaze on the fallen tree and find the overgrowth of scribe mark S and other illegible scribe marks.

Remark the original corner tree, 1/4 S10 on West face, and S11 on the East face.

from which new bearing trees

A Fir 22" dia., bears S.17½°E., 76 lks. dist., mkd. ¼ S11 BT.

A Fir 6" dia., bears S.74°W., 24 lks. dist., mkd. ¼ S10 BT.