

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, Contract #63 dated March 22, 1856 (DCSO records, Vol. 9 Page 3862)

Set 1/4 sec. post, from which
 A Laurel 10" dia., bears S.59°W., 110 lks.
 An Oak 18" dia., bears North 45 lks.

Bureau of Land Management resurvey by Lynn Roseberry, under Group #645, Survey July 1967/ September 1968 (DCSO records Volume 36 Page 14953)

Point for the 1/4 sec. cor, restored by the method of broken boundaries; there is no remaining evidence of the original corner.

Set a Iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd: T 25 S R 7 W

1/4 S 13
 S 24
 1968

from which
 A Fir 53" dia., bears N.23°W., 70 lks. mkd. 1/4 S13 BT.
 An Oak 37" dia., bears S.37°W, 94 lks. mkd. 1/4 S24 BT.

Found OK, Feb. 1996 by K. DeGroot - M 124-3

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1905, surveyed April/May 1999. (DCSO rec. Vol. 53 page(s) 20612)

The 1/4 sec. cor. of secs. 13 & 24, monumented with an iron post, 2 1/2" diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd. T 25 S R 7 W

1/4 S 13
 S 24
 1968

from which the bearing trees mkd. by Roseberry
 A fir, 53" diam., bears N.23°W., 46.2 ft. with a healed blaze.
 An oak, 40" diam., bears S.37°W., 62.0 ft. with a healed blaze.
and a new bearing tree
 A fir, 4" diam., bears S.26 3/4°W., 13.4 ft. mkd. X BT.
Cor. is located at the base of a steep west slope on the east side of a shelf.