

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12; & 6 & 7, T25-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, Contract #272, dated August, 1877
(DCSO records, Volume 9 Page 3849)

Set a Cedar post, 40" long, 4" dia. 1/3 in ground, for the
cor. to secs. 1, 6, 7 and 12, from which
A Fir 18" dia. bears N.60°E., 5 lks. dist.
A Fir 36" dia. bears S.2°E., 26 lks. dist.
A Fir 36" dia. bears S.2°W., 18 lks. dist.
A Fir 16" dia. bears N.40°W., 5 lks. dist.

Wm. P. Heyden, Contract #656, dated May 21, 1896. (DCSO
records Volume 9 Page 3851)

At the cor. of secs., 1, 6, 7 and 12, T.25S Rs 6 & 7W., which
is a post, marked & witnessed as described by the Surveyor
General. The post being badly decayed in its place, I set a
new Fir post, 4 ft. long, 5" sq., 36" in the ground marked
T 25 S S 6 on the NE., R 6 W S 7 on SE., R 7 W S 12 on SW. &
S 1 on NW. faces, with 5 notches on S. and 1 notch on N.
edges.
The original witness trees being in good condition, I make no
change.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy; Mike
Stone - July 1963 - C.S. File 49/123-92

Found - 38" Fir S.2°W., 11.9 ft. Faint bark scribing visible
"12 T26 7W". Axe marks visible at location for
BT.
36" Fir S.2°E., 17.2 ft. old axe marks visible on
bark (2 scars), no scribing.
24" Fir N.40°W., 3.3 ft. illegible scribe marks
visible on bark.
24" Fir N.60°E., 3.3 ft. Good axe scar visible. Did
not open. (distances are all from face of tree)
Set brass cap at cor. mkd: County Surveyor T25S R7W S1|S6 R6W
Office, 1963 S12|S7

Blaze & rescribed:

24" D.Fir N.55°E., 4.2 ft. mkd: T25S R6W S6 CS BT.
36" D.Fir S.5°E., 19.0 ft. mkd: T25S R6W S7 CS BT.
24" D.Fir N.38°W., 4.5 ft. mkd: T25S R7W S1 CS BT.
New BT - 16" D./Fir S.22°W., 21.8 ft. mkd: T25S R7W S12 CSBT.
Corner lies on gentle west slope approx. 80 ft. W. of top of
ridge.

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12; & 6 & 7 of T25-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bruce Shaner Engineering - For: Western Timber Company
July 28, 1989 - C.S. File 63/96 and RM 3-72

CORNER REPORT ONLY

Found - 1" I.P. with 2½" brass cap, (County, 1963)
38" D.Fir now a snag 10 ft. high, bears S.2°W.,
11.9 ft.
24" D.Fir now a 6 ft. high stump, face overgrown,
bears N.55°E., 4.2 ft.
36" D.Fir now a 6 ft. high stump, face overgrown
bears S.5°E., 19.0 ft.
24" D.Fir now a snag face overgrown, bears N.38°W.,
4.5 ft.
16" D.Fir now a 10 ft. high snag, face burnt off,
bears S.22°W., 21.8 ft.

Corner lies on a gentle west slope, approx. 80 ft. west of
dirt road along summit of Tye Mt.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 10/24/2007 - C.S. File 67/24-35

Found - 2½" dia., brass cap, properly mkd., on 1¼" O.D. iron
pipe. Projects 12" above ground, firmly set.
Steel fence post fd. to NE approx. 6" away.
38" now 37" dia., x 9 ft. tall D.Fir stump partial
bark scribe "6" visible bears S.2°W., 13.4 ft.,
11.9 ft. to face (1963 rec. S.2°W., 11.9 ft. to
face of tree) OBT
36" now 36" dia., x 8 ft. tall D.Fir stump, rotted
blaze, bears S.5°E., 19.0 ft. Note: Stump is
pistol butt. (Agrees w/rec.) OBT
24" now 24" dia., x 10 ft tall D.Fir snag, partially
healed blaze shows illegible scribe bears
N.55°E., 4.2 ft. (agrees w/1963 rec.) OBT
24" now 24" dia., x 6 ft tall D.Fir stump, burnt
face w/burling visible bears N.38°W., 4.5 ft.
(agrees w/1963 rec) OBT
16" now 12" dia. x 8 ft tall D.Fir stump, face burnt
off bears S.22°W. 21.8 ft (agrees w/rec) 1963 BT
Set - 6" dia., D.Fir double blazed & scribed "T25S R6W S7
CS BT" bears S.16½°E., 9.7 ft.
7" dia., D.Fir double blazed & scribed "T25S R7W S1
CS BT" bears N.84°W., 10.0 ft.
5" dia., D.Fir double blazed & scribed "X" on high
blaze & "CS BT" bears N.25½°E., 9.8 ft.
Note - Compass decl. 16¼°E.