

PRIMARY CORNER DESCRIPTION West 1/4 Sec. 16 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO resurvey by Morris Wygant, Compassman for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 10 Page(s) 3986)</p> <p>-----</p> <p>Set cedar post, 3 ft. long, 4" sq. 24" in the ground for ¼ sec. cor. of sec. 16 marked ¼ S16 on E face; from which A cedar, 12" dia., bears S.22°30'E., 36 lks. mkd: ¼ S16 BT A hemlock, 16" dia., bears N.3°E., 75 lks., mkd: ¼ S16 BT.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July/Aug 1968 - C.S. File 54/72-12</p> <p>-----</p> <p>Found - Orig. 12", now 18" Cedar, S.22½°E., 23.8 ft., alive, opened &amp; shows scribe. No trace of NE BT probably due to huge fir windfall.</p> <p>Set - Brass Cap at Car. mkd: County Surveyors T25S R8W Office, 1968 ¼   S 16</p> <p>New BTs- 12" Hemlock N.20°E. 37.0 ft. mkd. ¼ S16 CS BT. 14" Hemlock S.47°E. 43.3 ft. mkd. ¼ S16 CS BT.</p> <p>This corner lies 15 ft. S. of email creek, course N.E.</p>
<p>Ronald L Rice - Nov. 2016 - Roseburg Resources Co - M172-77</p> <p>-----</p> <p>Found - No monument found lost to slide. The following accessories were fd and used to set corner monument at record position by distance - distance intersection. 33" R.Cedar bears S.22½°E., 23.8' - healed face 26" Hemlock bears S.47°E., 43.3' - healed face Record 12" Hemlock bearing N.20°E., - Lost to slide.</p> <p>Set - 5/8"x30" rebar with 2½" aluminum cap marked T25S R8W ¼   S16 2016 54633LS</p> <p>New BT - 15" D.Fir bears N.6°W., 42.9' - blazed, scribed X BT ¼ corner to sec. 17 bears S.11°29'55"W., 186.84' Steel post adjacent to corner</p>