

PRIMARY CORNER DESCRIPTION Cor. Secs 22, 23, 26, & 27

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by - A.R. & S.C. Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 9 Page(s) 3944)

Cor. to secs. 22, 23, 26, & 27
Set cedar post 4 ft. long & 4" sq. from which a
 Fir, 16" dia., bears S.33°E., 26 lks.
 Fir, 6" dia., bears S.25°W., 23 lks.
 Fir, 8" dia., bears N.60°W., 371 lks.
 Fir, 24" dia., bears N.53°E., 25 lks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Mike Stone - Oct. 30 1962 - C.S. File 49/88-10

Found - 1" iron pipe & following BTs:
 38" Fir N.73°E. 16.5 ft. (to old face) bark scribing (looks like Flint's scribing) "T25S R8W". Gov't notes call for this BT to be N.53°E., 16.5 ft.
 Fir snag, broken off in Oct. 12th windstorm, now 33" dia., S.19°E., 17.2 ft. (to old face) old bark scribing "T2" rest of face destroyed. Gov't notes call for this BT to be S.33°E., 17.2 ft.
 No trace of NW or SW BTs, impossible to get bearings & distances to ft Gov't notes on 2 BTs found.
DID NOT SET BRASS CAP
New - Reblaze & scribe 38" D.Fir N.73°E., 17.5 ft. (to center) Mkd: T25SR8WS23 CS BT
 5" hemlock S.44°E., 34.4 ft., mkd: "S26 CS BT"
 7" hemlock N.54°W. 4.1 ft. mkd: "T25S R8W S22 CS BT"
 6" hemlock S.61°W., 38.0 ft., mkd: "T25S R8W S27 CS BT"
Corner lies on very steep NE slope.

BLM dependent resurvey by Donald R. Beck & John M. Jelley, Cadastral Surveyor, under group #'s 350 & 563 surveyed Sept. 1964/July 1965 - (DCSO records 33 Page(s) 13772)

The cor. of secs. 22, 23, 26, & 27, perpetuated & recorded by Godfrey in 1962, monumented with an iron pipe, 1" dia. firmly set, protruding 6" above ground, from which the remaining orig. BTs:
 A fir, 38" dia., bears N.73°E., 25 lks., with scribe marks T 2 visible on a bark blaze. This tree was remarked by Godfrey alongside the orig. blaze. This blaze is now partially healed. (Rec. bearing N.53°E.)
 A fir snag, 34" dia., bears S.18½°E., 26 lks. with partial scribe marks visible on a bark blaze. (Rec. bearing S.33°E.)
continued next page

TOWNSHIP 25 RANGE 08 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Cor Secs 22, 23, 26, & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

and BTs marked by Godfrey

A hemlock, 5" dia., bears S.44 $\frac{3}{4}$ °E., 52 lks., mkd: S26 CS
BT on a double blaze.

A hemlock, 8" dia., bears S.66 $\frac{3}{4}$ °W., 57 lks., mkd: T25S R8W
S27 CS BT on a double blaze.

A hemlock, 8" dia., bears N.56°W., 6 lks., mkd: T25S T8W
S22 CS BT.

At the corner point

Set an iron post, 28" long, 2 $\frac{1}{2}$ " dia., 23" in the ground, with
brass cap marked:

T25S	R8W
S 22	S 23
S 27	S 26
1965	

from which a new BT

A fir, 37" dia., bears N.24 $\frac{3}{4}$ °E., 68 lks., mkd: T25S R8W
S23 BT.

Ron Quimby - 4/2017 - June 2017 - C.S. File 65/95-36

Condition report only

Found - BLM brass cap per rec.

14" Hemlock (orig. 5") S.44 $\frac{3}{4}$ °E., 34.3 ft. good scar.

20" Hemlock (orig. 8") S.66 $\frac{3}{4}$ °W., 37.6 ft. good scar.

20" Hemlock (orig. 8") N.56°W., 4.0 ft. good scar.

48" Fir (orig. 37") N.24 $\frac{3}{4}$ °E., 44.9 ft. good scar.

Compass decl. 15 $\frac{1}{2}$ °E.