



TOWNSHIP 25 RANGE 08 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 2; & Sec. 35, T24-8

|       |       |             |       |
|-------|-------|-------------|-------|
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |

A Fir snag 12" dia., bears S.45°E., 26 lks. dist., no marks visible on an opened blaze.

A Fir stump 30" dia., bears N.8°W., 28 lks. dist., bark scribed marks 3 B visible.

and the remains of a bearing tree mkd. by Byron:

A Cedar stump 25" dia., bears S.70°W., 58 lks. dist., with scribe marks BT visible on partially healed blaze.

and a bearing tree mkd. by Rogers in 1965:

A Cedar 13" dia., bears N.31°E., 81½ lks. dist., with a healed blaze.

and a new bearing tree:

A Fir 18" dia., bears S.12°W., 18 lks. dist., mkd. ¼ S2 BT Corner is on level, swampy ground.

Bruce Shaner - Dec. 7, 2000 - C. S. File 65/33-20

Found - 2½" brass cap, properly marked, on a 1" iron pipe, from which a:

25" Cedar BT, now stump, bears S.70°W., 38.3 ft. (scribes not visible)

18" Cedar BT, face overgrown, bears N.31°E. 53.8 ft.

24" D.Fir BT, (rec. 18") bears S.12°W., 11.9 ft., face overgrown.

Other BTs now gone.

Set - 2 each 6 ft. steel fence posts:

1 at south, 1.0 ft.

1 at west, 1.0 ft.

Note - Corner is north a distance of 100 ft. from E-W logging spur road.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 3/18/26 - C.S. File 67/62-25

Found - 2½" DCSO brass cap on iron pipe.

County Surveyors Office

¼ S 35 T24S R8W

S 2 T25S R8W

1958

25" x 1 ft. rotted sawn cedar stump S.70°W. 38.3 ft.

21" cedar N.31°E. 53.8 ft. healed face.

29" down D. Fir (Rec. S.12°W. 11.9 ft.)

2 - steel fence posts

South 1.0 ft.

West 1.6 ft.

UNRECORDED - 6" D.Fir, north 11.0 ft Unmarked, has R.R. tag  
Compass decl. 14¼°E.

TRIMBLE GEO XT POSITION

43°.43252703 N. 123°.61424566 W.