

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24 only, T26-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 10 Page(s) 4065-66)

-----  
Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 13, 18, 19 and 24, marked T26S S18 on NE.; R1W S19 on SE.; R2W S24 on SW.; and S13 on NW. faces, with 3 notches on N. and S. edges, from which  
A Fir 8" dia., bears N.45°E., 34 lks. dist. mkd. T26S R1W S18 BT.  
A Fir 6" dia., bears S.15°E., 14 lks. dist. mkd. T26S R1W S19 BT.  
A Fir 10" dia., bears S.14°W., 12 lks. dist. mkd. T26S R2W S24 BT.  
A Fir 6" dia., bears N.60°W., 14 lks. dist. mkd. T26S R2W S13 BT.

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4087)

-----  
The cor. of secs. 13, 18, 19 and 24 bears West 55 lks. dist., no trace of the post is found. All the BTs are standing but are deeply overgrown.  
I re-establish the cor. in its original position as the cor. of secs. 13 and 24, T26S R2W only, as follows:  
Set a basalt stone 18x12x8 ins., 12" in the ground for cor. of secs. 13 & 24, marked with 3 notches on N. and S. edges, from which  
A Fir 15" dia., bears S.14°W., 12 lks. dist. mkd. T26S R2W S24 BT.  
A Fir 10" dia., bears N.60°W., 14 lks. dist. mkd. T26S R2W S13 BT.  
Marks on former bearing trees referring to T26S R1W are sufficiently obliterated.

GL0 survey by C.M. Collier, Deputy Surveyor, under Instructions dated May/Sept. 1913 - (DCSO records Vol. 10 Page(s) 4263)

-----  
Found stone, firmly set, marked and witnessed as described by the surveyor general.

GL0 Survey by Fred Mensch, U.S. Surveyor Under Special Instructions dated May 25, 1916 - (DCSO records Vol. 10 Page(s) 4286)

-----  
(Cont. Next Page)

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 100404

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24 only, T26-2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Intersect the original McQuinn cor. established in 1883, as the cor. of secs. 13, 18, 19 and 24, and reestablished 1910 by Deputy Mensch as the cor. of secs. 13 & 24 only. This cor. is a basalt stone, 4x10x8 ins. above ground, firmly set, mkd. and witnessed as described by the surveyor general.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - and crew - March 29, 1963 - C.S. File 52/77-12

-----  
Found - Pile of rocks at corner, chisel mark "--" on one of them.  
20" Fir N.67°W., not N.60°W., 9.2 ft., cut open and found good scribing.  
20" Fir S.27°W., not S.14°W., 7.9 ft., opened and found old face badly rotted. No scribing visible. This tree was opened approx. 50 yrs. ago & looked as if scrbg was chopped off at that time  
No trace of original NE. and SE. trees.

Set Brass cap at cor. mkd: County Surveyors Office

T 26 S  
R2W S 13 | R1W  
S 24 |  
1963

New BT - 9" D.Fir S.63°W., 11.4 ft. mkd. T26S R2W S24 CS BT.  
Rescribe 20" D.Fir N.67°W., 9.2 ft. mkd. T26S R2W S13 CS BT.  
Cor. lies approx. 130 ft. North of North Umpqua Highway.

Fd. OK, Feb. 1981 by G. Grubb - M 86-68

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Nov. 26, 1984 - C.S. File 62/21-9

-----  
Found - 1963 DCS0 brass disk on a 1" I.P. protruding 15" above ground in a 2 ft. dia. mound of stone. Cap properly mkd.  
A 16"x10"x8" stone found with 3 notches possible on one edge. (1910 survey)  
6" now a 23" D.Fir with a double well healed blaze, bears N.67°W., 9.2 ft. (Orig.)  
10" now a 21" D.Fir with one chopped out and rotted blaze, no scribing visible and a double well healed blaze, bears S.27°W., 7.9 ft. (Orig.)  
9" now a 10" D.Fir with a single well healed blaze, bears S.63°W., 11.4 ft. (1963 BT)

New BT - 8" Hemlock double blazed and scribed "T26S R2W S13 CS BT" bears N.9½°W., 16.5 ft.  
Corner lies approx. 100 ft. N. of Hwy. 138 on a S. slope.

cont.

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 100404

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24 only, T26-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

James M. Stanley, ODOT - Sept/Nov. 2007 - St. Hwy 138-011C  
-----

Fd. 2½" Brass dist stamped DOUGLAS COUNTY SURVEYORS OFFICE  
stamped "T2S R1W R2W S13 S24 1990" (9-25-07)

N. 604371.651

E. 4290210.112

BLM dependent resurvey by Jeffrey O. Covington, Cadastral  
Surveyor, under Group No. 2923, surveyed July 2018/March  
2020- (DCSO records Vol. 59 Pages 24042)  
-----

At the cor. of secs. 13 and 24 only, reported by Mensch in  
1916-18; perpetuated by Godfrey, in 1963; subsequently  
perpetuated by Monrean, in November, 1984; monumented with an  
iron post, 1" dia., firmly set, projecting 15" above ground,  
in a mound of stone, 2 ft. base, 12" high, with a brass cap  
(properly) mkd.

from which the remains of the BTs reported by Mensch

A fir snag, 23" dia., bears S.27¼°W., 7.9 ft., with no  
marks visible on open decayed blaze. (Original)  
(Record, S.14°W.)

A fir, 33" dia., bears N.71½°W., 9.2 ft., with a healed  
blaze. (Original) (Record, N.60°W.)

and a bearing tree mkd. by Godfrey

A fir, 13" dia., bears S.60¾°W., 12.5 ft., with a healed  
blaze.

and the remains of a bearing tree mkd. by Monrean

A roothole bears N.9¾°W., 15.9 ft., alongside of which is  
a down hemlock, 12" dia., with a healed blaze.