TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4165)

A fir, 10" dia., for ¼ sec. cor., I mark ¼ S6 on N & 7 on S side, from which
A cedar, 14" dia., bears N.3°E., 8 lks., mkd: ¼ S6 BT.
A hemlock, 10" dia., bears S.65°E., 12 lks., mkd: ¼ S7 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - D. Schulze - June 1972 - C.S. File 54/94-113

Found - Decayed remains of old Corner Tree, no scribing.
Orig. BT to SE gone, only stump hole remains.
Orig. l4", now 18" Cedar N.3°E. 5.3 ft., alive, good scribe visible "T" at top of nearly healed blaze.
We remove remains of old Corner Tree &
Set - Brass Cap Mkd: County Surveyors Office 1972 T26S R1W ¼ S 6 / S 7

New BT - 12" Hemlock S.44°E. 7.2 ft. scribed "¼ S7 CS BT". This corner lies 6 ft. East of creek, course South.