

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Cor Secs 19, 20, 29, & 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4153)

Point for cor. of secs. 19, 20, 29, & 30 falls on a basalt bolder 3x2x2 ft., on which I cut a cross (X) at exact cor. point, with 2 notches S & 5 notches E of cross, from which
A cedar, 18" dia., bears N.69°E., 109 lks., mkd: T26S R1W S20 BT.
A cedar, 30" dia., bears S.11°E., 55 lks., mkd: T26S R1W S29 BT.
A fir, 36" dia., bears S.77°W., 119 lks., mkd: T26S R1W S19 BT.
A fir, 28" dia. bears N.78°W. 77 lks. mkd: T26S R1W S19 BT

Fd. & used on GLO corrective survey by Fred Mensch, US Surveyor, under Group No. 16, surveyed June/Nov. 1916 - (DCSO records Vol. 10 Page(s) 4173)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Sept. 1970 - C.S. File 52/77-20

Found - Orig. 30", now 36" Cedar, alive, S.11°E., 36.3 ft., scribe visible on nearly healed blaze. (To be removed by road const)
Corner Stone buried under clearing debris several ft
Other bearing trees gone.
Because of road to be built over corner, we chain East 110 ft.
Set - Brass Cap at WC mkd: County Surveyors T 26 S R 1 W
Office 110 ft. S 19 | S 20
1968 W to Cor S 30 | S 29
New BTs- 5" Hemlock N.63°W. 22.6 ft. mkd WC S19 CS BT.
16" Hemlock N.72°E. 25.0 ft. mkd: WC T26S R1W S20 CS BT
20" Hemlock S.63°E. 27.3 ft. mkd: WC T26S R1W S29 CS BT.
20" Cedar S.38°W. 21.5 ft. Mkd: WC T26S R1W S30 CS BT.
Witness Corner lies 20 ft. E. of R/W Line East of Roadway.