

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCS0 records Vol. 10 Page(s) 4164)

Set a conglomerate stone 18x9x6", 12" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which
 A chinquapin, 6" dia., bears S.78°E., 36 lks. mkd: ¼ S8 BT
 A fir, 24" dia., bears N.6°W., 84 lks., mkd: ¼ S7 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - March 1970 - C.S. File 52/77-30

Found - Corner Stone, in place, and mkd: "+" on top & "¼" on west face.
 Orig. 24", now 50" Fir, alive, N.6°W. 55.4 ft., prev, opened, scribe visible.
 We find a hole & pieces of Chinquapin where SE Orig. BT. should be.
Set - Brass Cap at Cor. Mkd: County Surveyors T26S R1W (Reset Stone alongside) Office 1970 ¼ S 7|S 8
New BTs- 12" D.Fir S.82°W. 5.9 ft. mkd: "¼ S7 CS BT".
 14" D.Fir N.51°E. 10.7 ft. mkd: "¼ S8 CS BT".
This corner lies on bench at S.W. Corner of cutoff area.

Jack White, S&F Land Services - For: USDA Forest Service Region 6 - 1/2025 - M185-80 A&B

Found - Held an iron pipe, 1" dia., with a 2½" brass cap, from which
 Dead, fire damaged BTs:
 54" D.Fir stump bears N.6°00'W., 55.4'.
 16" D.Fir stump bears S.85°W., 5.9' (S.82°W.)
Set two reference monuments - Rebar, 5/8" dia., 30" long, with a yellow plastic cap mkd: S&F Land Services: Bearing N.47°42'05"E., 43.55' and N.45°58'41"W., 28.25'.