

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4138)

Set a basalt stone 12x10x6", 8" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which

A fir, 16" dia., bears N.16°E., 12 lks., mkd: ¼ S28 BT.

A fir, 20" dia., bears S.12°W., 22 lks., mkd: ¼ S33 BT.

Arthur Boyer - Witness: Mr. Caldwell of the USFS & Joe Forest, Pac. Plywood - For: Pacific Plywood, Dillard OR - Nov. 30, 1959 - C.S. File 51/64

Found - Mkd. Stump of Orig. BT which is shown in orig. govt. notes a being 20" Fir S.12°W. 22 lks. or 14.5 ft. from the ¼ corner. This stump is still good shape and is now 38" in dia. Measured the corner from where the face of the blaze would be if the tree were a 20" tree and at N.12°E. 14.5 ft. from this stump, set a 1½" Iron Pine, 40" long leaving it about 12" out of the ground with rocks piled around it. This stump will be in good evidence for a long time for renewing the corner or finding this pipe.

Blazed and scribed -

11" Yew Tree S.26°W. 23 ft & marked it ¼ S33 T26S R1W. 1581 BT.

Blazed, (on one long blaze) a 30" Fir and scribed it ¼ S28 T26S R1W 1581 BT. It is measured on slope, N.40°E. 266.5 ft. from the corner or 255.3 ft. measured on a horiz. or level msmt. This tree is below a road & on a slope averaging abt. 23°, it is on the south edge of a cutting: close trees were not available.

The corner is hard to locate, although there is little brush there now. It is on a side hill which faces N. and is about 40 ft. S. of a road and about 15 ft. above the road, vertically. The Yew Tree mentioned is easy to find, it is alone on the side hill. The corner pipe and the Fir BT are not easy to find, nor the stump of the orig. BT.