

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 21

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GL0 survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCS0 records Vol. 10 Page(s) 4142)

Set a conglomerate stone 18x12x6", 12" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which
A fir, 30" dia., bears N.78°W., 22 lks., mkd: ¼ S16 BT.
A fir, 24" dia., bears S.40°E., 45 lks., mkd: ¼ S21 BT.

Dennis Gaylord, USFS & Deputy Co. Surveyor - Witness: Roland Simshauser - Jan. 26, 1978 - C.S. File 59/46-7

Found - Orig. corner stone is set solidly in place. Stone, 16x12x6", is mk. "X" on top and "¼" on north face 30" now 37" D.Fir bears N.81°30'W., (Rec. N.78°W.) 15.2 ft (Rec. 14.52 ft.) Has a healed blaze. This tree is nearly dead.
A 29" D.Fir stump bears S.40°E., 29.7 ft. to the face. Reverse scribing visible "S21 BT".
Set - Moving orig. stone monument aside, I set in its place a 2½" brass cap on a 1" G.I. pipe. Cap stamped County Surveyors Office T26S R1W ¼ S16 S21 1978. I bury the cor. stone alongside.
New BTs- A 11" D.Fir bears S.74°30'W., 13.5 ft. scribed "¼ S21 on a double blaze.
A 9" D.Fir bears N.57°E., 29.2 ft. scribed "¼ S16 CS BT" on a double blaze.
Corner lies on south edge of clearcut unit.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flauser and Jeff Lorsung - 2/25/26 - C.S. File 67/62-17

Found - 2½" D.C.S.O. brass cap on 1" Iron pipe proj.
DOUGLAS COUNTY
T26S R1W
1 S16
4 S21
1978
SURVEYORS OFFICE
Burned - dead 37" D. Fir N.81°30'W. 15.2 ft. healed blaze. Add 3½" mag nail right side center.
D. Fir stump S.40°E. 29.7 ft. roots and bark remain. 8" x 2½" stub down and rotted S.74°30'W. 13.5 ft.
Found scribing "CS BT"
12" D. Fir N.57°E. 29.2 ft. fully healed double blaze.
New - Burned - dead 33" D. Fir N.65°E. 30.4 ft. Add 3½" mag nail right side center.

Continued next page

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Burned - dead 6" R. Cedar N.22°W. 12.5 ft. Add 3½" mag
nail right side center.
Notes - Area burnt 9/2020.
Monument on small flat bench near top of S.W.
running draw. N.E. quadrant is burned old
growth. Rest is older reprod. Mon is approx.
700 ft. west of graveled forest road.
Compass decl. 14¼°E.
TRIMBLE GEO XT POSITION
43°.29904178 N. 122°.82531381 W.