

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 457700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only, T25-1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Hezekiah H. Johnson, Deputy Surveyor, under Contract #721, dated May 1, 1900 - (DCSO records Vol. 8 Page(s) 3502)

-
- A Fir 9" dia., for cor. of secs. 3, 4, 33 and 34, I mark T25S S34 on NE.; R1W S3 on SE.; T26S S4 on SW.; and S33 on NW. faces, with 3 notches on E. and W. sides, from which
- A Fir 8" dia., bears N.55°E., 21 lks. dist. mkd. T25S R1W S34 BT.
 - A Fir 12" dia., bears S.45°E., 1 lks. dist. mkd. T26S R1W S3 BT.
 - A Maple 5" dia., bears S.86°W., 27 lks. dist. mkd. T26S R1W S4 BT.
 - A Fir 6" dia., bears N.45°W., 12 lks. dist. mkd. T25S R1W S33 BT.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 9 Page(s) 3573) and duplicate Pg. 4079A)

The cor. of secs. 3, 4, 33 and 34, which is a Fir 10" dia., marked and witnessed as described by the surveyor general, bears S. 47 lks. I re-establish this cor. as the cor. of secs. 33 and 34, T25S R1W only, by obliterating marks on bearing trees referring to T26S.