

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4121)

-----  
A fir, 40" dia., for ¼ sec. cor. I mark ¼ S11 on N & 14 on S side, from which

A fir, 36" dia., bears N.43°E., 30 lks., mkd: ¼ S11 BT.

A cedar, 16" dia., bears S.74°E., 40 lks., mkd: ¼ S14 BT.

-----  
Dennis Gaylord, USFS & Deputy Douglas Co. Surveyor - Randal Lopez & Jim Talburt, Witnesses - Feb. 1978 - C.S. 59/46-9

-----  
Found - A 29" badly decomposed Fir snag. An unhealed blaze on the South side with scribing "14" visible. Axe marks on bark on the North side & no scribing remaining.

A 38" (Rec. 36") Fir snag bears N.43°E., 18.7 ft. Scribing visible "¼ S11 BO", on partly decomposed face. (Rec. distance is 19.8 ft.).

The orig. BT to the SE is gone.

Set - Removing the remains of the orig. corner tree, I SET a 2½" brass cap on a 1" galv. I.P. stamped:  
County Surveyors Office

¼ T26S R1W

S11 1978

S14

BTs - A 10" D.Fir bears N.11°E., 12.6 ft. scribed "¼ S11 CS BT on a double blaze.

A 20" D.Fir bears S.79°30'E., 27.7 ft. scribed "¼ S14 CS BT" on a double blaze.

Placed County BT signs on both trees.