

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor. Secs. 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4111)

Set a basalt stone 15x10x5", 10" in the ground for cor. of secs. 1, 2, 11, & 12 mkd with 1 notch on E & 5 notches on S edge, from which

An alder, 10" dia., bears N.85°E., 10 lks., mkd: T26S R1W S1 BT.

An alder, 15" dia., bears S.51°E., 24 lks., mkd: T26S R1W S12 BT.

A cedar, 7" dia., bears S.58°W., 16 lks., mkd: T26S R1W S11 BT.

A maple, 10" dia., bears N.14°W., 15 lks., mkd: T26S R1W S2 BT.

Reported as not found on the old cor. renewal visual - could not find any CS file with info about a report. Usually when there is a not fd. symbol on the map the search was done by the DCSO in the 1960's or 1970's