TOWNSHIP 26 RANGE 02E POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35, WC

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Otto S. Draper, U.S. Transitman, under Special Instructions dated Dec. 24, 1920, surveyed Sept. 1929/Aug. 1930 - (DCSO records Vol. 23 Page(s) 9660

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for ¼ cor. of secs. 26 & 35, with brass cap mkd

¼ S26/S35 1929

from which
A fir, 12" dia., bears S.54°W., 68 lks., mkd: ¼ S35 BT.
A cedar, 10" dia., bears N.74°W., 79 lks., mkd: ¼ S26 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage, V. Perron, J. Powell - Feb. 13, 1968 - C.S. File 52/43-3

Found - 1929 GLO Brass Cap in good condition, properly mkd.
Orig. 12", now 15" Fir, alive, S.54°W. 44.9 ft., shows good scar. We do not open. This tree falls inside of R/W for new road.
Orig. 10", now 12" Cedar, alive, N.74°W. 52.1 ft., scribe marks visible on partially healed blaze.
Move Brass Cap 40 ft. north of true corner point and Reset, Add mks. "Wit. Cor. 40 ft. S. to Cor." & drive 5/8" I.P. at true corner point.

New BTs- 13" W.Fir S.67°E. 9.0 ft. mkd. W.C. ¼ S35 CS BT.
15" W.Fir N.40°E. 6.8 ft. mkd. W.C. ¼ S26 CS BT.

Note - Wit. Corner lies on top of ridge, course E. & W.
True Corner lies on N. edge of R/W - 100' N. of new road, as constructed
Orig. 12" Cedar bears S.64°W. 56.9 ft. from Witness Corner.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & V. Perron - 11/4/1969 - C.S. File 52/43-36

Fd ok WC & true cor. to ¼ 26/35 brass cap 40 ft N for WC - IR at true corner - the true cor. is 100 ft. N of new road as constructed.