

PRIMARY CORNER DESCRIPTION Cor. #3 HES 227

Alias	Description

HES No. 142 by Frank D. Maxwell, Forest Service Surveyor, under special instructions dated April 27, 1914 - Surveyed July 1914 - DCSO records Vol. 28 Page(s) 12179)

Cor. No. 3 of the listing survey, which I destroy and in its place establish cor. No. 3 of this survey, 160 ft. below cor. No. 2, as follows:
Set a porphyry stone, 24x10x6", 14" in the ground, over a stone marked with a cross for cor. No. 3 of this survey, marked 3 HES 227 on side facing the claim; from which
 A fir, 13" dia., bears N.3°45'E., 37 lks., marked X 3 HES 227 BT.
 A fir, 10" dia., bears S.79°00'W., 33 lks., marked X 3 HES 227 BT.
Raise a mound of earth 4 ft. base, 2 ft. high, 3½ ft. within the claim.

GLO Survey by Otto S. Draper, U.S. Transitman, under Special Instructions dated Dec. 24, 1920, surveyed Sept. 1929/Aug. 1930 - (DCSO records Vol. 23 Page(s) 9725

Cor. No. 3 HES 227, which is a stone, 10x10x6" above ground, marked and witnessed as described in the official record.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey & Clete Putnam - Aug. 6, 1960 - C.S. File 52/43-1

Found - 18"x12" stone at corner chiseled HES 227, from which
 23" Fir bears S.79°W., 21.5 ft. shows good scar.
 31" Fir bears N.5°E., 24.2 ft. shows good scar.
 I open SW BT & find good scribing 3 HES 227.
Note - Corner is located in about center of roadway now under construction. I set Wit. Cor. 40 ft. East of true corner.
Set - Brass cap at Wit. Cor. mkd: COUNTY SURVEYORS OFFICE 1960 WIT COR. 40' WEST TO 3 HES 227 T26S R2E
New BTs- 12" Cedar bears S.7°E., 23.7 ft. scribed 3 HES 227 CS BT.
 9" R.Fir bears N.41½°E., 32.8 ft. scribed 3 HES 227 CS BT.

DCSO (VRT) Fd. OK 10/1969 - C.S. File 52/43-7

continued next page

1

TOWNSHIP 26 RANGE 02E POINT IDENTIFIER # 927030

PRIMARY CORNER DESCRIPTION Cor #3 HES 227

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Robert Dean, LS 1808 - For: USFS - Dec. 20, 1984 - M98-6 & C.S. File 58/204-11

Found - 3/4" brass disc in 1 1/4" iron pipe (per C.S. 51/126) at corner, 3' deep in east shoulder of Road #4760.

Set - A 4"x4"x96" creosoted post over the iron pipe, from which:

A 1" galvanized iron pipe with 2 1/2" brass cap, mkd: COUNTY SURVEYORS OFFICE WIT COR. HES 227 40' WEST TO COR 3 T26S R2E 1960, bears S.89°57'E., 39.75' (rec. East 40.00' per 1960)

A 13" D.Fir, good scar, bears N.67°32'E., 65.7' (rec. N.41 1/2°E., 32.8' per 1960 ren) from WC N.39°51'E., 32.8' (my measurement)

A 17" cedar, good scar, bears S.61°29'E., 48.3' (rec. S.7°E., 23.7' per 1960 ren.) from WC S.6°45'E., 23.2' (my measurement)