

PRIMARY CORNER DESCRIPTION Cor. No. 1 HES 178

Alias	Description
Alias	Description
Alias	Description
Alias	Description

HES No. 178 by Frederick W. Rase, Forest Service Surveyor, under special instructions dated December 17, 1915 - Surveyed Aug. 1916 - DCSO records Vol. 28 Page(s) 12169)

Cor. No. 1 of this survey, identical with cor. No. 7 of listing survey, a pine tree 30" dia. I destroy all listing survey marks and mark the tree 1 HES 178 on side facing claim, from which

An Oak, 14" dia., bears S.39°40'W., 53 lks., mkd. X 1 HES 178 BT.

A fir, 14" dia., bears N.38°16'W., 49 lks., mkd. X 1 HES 178 BT.

Raise a mound of earth 4 ft. base, 2 ft. high, 3½ ft. dist. within the claim.

USLM No. 142 bears N.52°59'E., 31.34 chs.

Cor. No. 4 of HES Ho. 142 (accepted) bears N.8°45'E., 13.47 chs. (direct measurement)

Note - See C.S. 63/5 for copy of "Listing Survey" notes.

GLO Survey by Otto S. Draper, U.S. Transitman, under Special Instructions dated Dec. 24, 1920, surveyed Sept. 1929/Aug. 1930 - (DCSO records Vol. 23 Page(s) 9725

Cor. No. 1 HES No. 178, which is a pine, 32" dia., marked & witnessed as described in the official record.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & V. Perron - Oct. 28, 1969 - C.S. File 52/43-15

Found - Orig. 30" now 32" Pine corner tree. Opened & "S178" visible.

Orig. 14" now 16" Oak snag, S.39°40'W., 35.0 ft. scribe vis. on unhealed blaze.

Orig. 14" now 32" D.Fir, alive, N.38°W., 32.3 ft. shows good scar. We tag.

Set - At base of cor. tree, 24" W of center: Brass cap mkd
COUNTY SURVEYORS T26S R2E
OFFICE 1969 COR. #1 HES 178

New BTs- 12" D.Fir, N.74°W., 31.2 ft. mkd: "1 HES 178 CS BT"
15" D.Fir, S.62°W., 7.4 ft. mkd: "1 HES 178 CS BT"

This corner lies on southerly side of old Illahee Rd, course NE bear. & dist. from center of corner tree.

Robert L. Dean, LS 1808 - For: USFS - Dec. 20, 1984 - M98-6 & C.S. File 58/204-11

Found - 28" P.Pine, scribing visible low from which:
continued next page

TOWNSHIP 26 RANGE 02E POINT IDENTIFIER # 978010

PRIMARY CORNER DESCRIPTION Cor. No. 1 HES 178

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A 1" galvanized iron pipe with 2½" brass cap,
(properly) mkd, bears S.66°00'W., 1.47' (rec.
West 2.0' per 1969 ren.)
A fallen 14" oak snag bears S.42°00'W., 36.6' (rec.
S.39°40'W., 34.98' per HES 178)
A 19" D.Fir, good scar, bears S.55°20'W., 7.1' (rec.
S.62°W., 7.4' per 1969 ren)
A 13" D.Fir, good scar, bears N.76°00'W., 30.8' (rec
N.74°W., 31.2' per 1969 ren.)
A 34" D.Fir, good scar, bears N.37°40'W., 32.7' (rec
N.38°16'W., 32.34' per HES 178)
I add figures " ↗ RM LS 1808" to cap.