

PRIMARY CORNER DESCRIPTION Cor. No. 9 HES 93

Alias	Description

HES No. 93 by Frank D. Maxwell, Forest Service Surveyor, under special instructions dated July 7, 1913 - Surveyed July 1914 - DCSO records Vol. 28 Page(s) 12162

Cor. No. 9, 150 ft. below spur ridge, identical with Cor. H/8 of listing survey, a stone, mkd. & witnessed as described by Asher Ireland, Assistant Forest Ranger; in place of which I set an igneous stone, 24x14x6", 14" in the ground, for Cor. 9, mkd. 9 HES 93 on SW face, with a cross (+) on top, from which

 A fir, 30" dia., bears N.8°30'E., 76 lks.
 A fir, 28" dia., bears S.48°00'W., 29 lks.
Both trees blazed and scribed 9 HES 93 BT.

GLO Survey by Otto S. Draper, U.S. Transitman, under Special Instructions dated Dec. 24, 1920, surveyed Sept. 1929/Aug. 1930 - (DCSO records Vol. 23 Page(s) 9729

Cor. No. 9 HES No. 93, which is a stone, 6x13x10" above ground, firmly set, marked & witnessed as described in the official record.

Marvin C. Ramsey - For: J.H. Baxter & Co. - Witnesses: J. Goodin & R. Schultz - Sept. 12-22, 1960 - C.S. File 51/126

The corner stone has been disturbed by a logging operation; determine the cor. point from the orig. BTs:

 30" D.Fir sawed stump bears N.48°W. 29 lks. mkd 9 HES 93 BT
 36" D.Fir sawed stump bears N.8½°E., 76 lks., with blaze healed.

Set an IP 3' long 1½" dia., 28" in the gr. mkd. RS404 from which

 18" D.Fir bears N.81½°W., 68 lks. mkd. 9 HES 93 RS404 BT.
 8" D.Fir bears S.79°E., 31 lks. mkd. 9 HES 93 RS404 BT.

Robert Dean, LS 1808 - For: USFS - Jan. 25, 1985 - M98-27 & C.S. File 63/5-3

Found - 1¼"x32" galvanized iron pipe with 3/4" brass disc stamped "RS 404", per 1960 ren., from which

 A 14"x13"6" stone, mkd "H9" lies west 0.5±;
 43" D.Fir stump, face visible, bears N.9°19'E., 47.21' (record N.8°30'E., 50.16' per HES 93)
 12" D.Fir, healed scar, bears S.78°45'E., 20.3' (rec. S.79°E., 20.46' per 1960 ren.)
 36" rotted D.Fir stump, bears S.20°15'E., 10.9' (S.19°E., 8.58' per listing survey)

continued next page

TOWNSHIP 26 RANGE 02E POINT IDENTIFIER # 993090

PRIMARY CORNER DESCRIPTION Cor. No. 9 HES 93

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

New -	38" rotted D.Fir stump, bears S.46°10'W., 18.4' (rec. S.48°W., 19.14' per HES 93) 24" D.Fir, healed scar, bears S.81°00'W., 44.4' (rec. N.81½°W., 44.88' per 1960 ren.) In place of the 1¼"x32" iron pipe I set a 2"x30" magnetic alum. monument, marked LS 1808 9HES93 (T26S R2E 1985. The iron pipe is inside the new monument. The orig. stone is now made part of a 36" cairn around the new monument.