

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 100560

PRIMARY CORNER DESCRIPTION N. 1/16 Cor. S. 7; & S. 12 of T26-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Doug. County Surveyors Office - Gary Langlitz; Larry Monrean;  
S.J. Flause; F.C. Silagy - March 1978 - C.S. 60/7; M 65-73

-----  
Set - Corner location determined by survey. At the corner  
point SE SET a 1" x 30" I.P. 28" in the ground,  
with brass cap attached marked:  
Douglas Co. Surveyor 1978  
T 26 S  
N 1/16  
S 12 | S 7  
R 3 W R 2 W

BTs - 12" R.Cedar scribed "N 1/16 S12 CS BT" on a double  
blaze, bears N.51°W., 28.5 ft.  
16" D.Fir scribed "N 1/16 S12 CS BT" on a double  
blaze bears S.34°W., 26.8 ft.

Corner located approx. 50 ft. south of Road #26-2-7.1

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff  
Lorsung- 11/8/2022 - C.S. File 67/55-5

-----  
Found - 2½" brass cap on 1" iron pipe flush with ground in  
rough stone mound, (properly mkd.)  
Burned-sawn 30"x2 ft. R.Cedar stump N.51°W., 28.5  
ft. lower blaze, good scar, 3½" mag nail top  
center. 1978  
Burned-sawn 31"x 2 ft. D.Fir stump S.34°W., 27.1 ft  
(rec 26.8 ft) 3½" mag nail top center, healed  
lower blaze. 1978

New - Burned-dead 14" hemlock S.51°E., 22.3 ft., 3½" mag  
nail right side center.

Note - Area burnt 9/2020  
Compass decl. 14½°E.  
Mon on moderate south slope just south of broad  
bench and 155'± North or power line access rd.

OCRS Coordinate system  
Cottage Grove - Canyonville Zone NAD 88  
N 179564.416  
E 255082.801