

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32; 5 & 6, T27-2

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by S.C. Flint, Contract #459, dated August 3, 1882
 - (DCSO records Vol. 10 Page(s) 4181)

Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor.
 to secs. 5, 6, 31 and 32, marked T26S R2W S32 on NE.; T27S
 R2W S5 on SE.; T27S R2W S6 on SW.; T26S R2W S31 on NW. faces,
 5 notches on the E. and 1 notch on the W. edges, from which

- A Cedar 12" dia., bears S.80°W., 18 lks. dist. mkd. T27S
 R2W S6 BT.
- A Cedar 16" dia., bears N.45°W., 32 lks. dist. mkd. T26S
 R2W S31 BT.
- A Cedar 12" dia., bears N.80°E., 36 lks. dist. mkd. T26S
 R2W S32 BT.
- A Cedar 20" dia., bears S.55°E., 31 lks. dist. mkd. T27S
 R2W S5 BT.

Fd. & used in GLO survey by CM Collier, Dep Surveyor, under
 Instructions dated May/Sept. 1913 - (DCSO rec Vol 10 Pg 4258)

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
 July 1967 - C.S. File 54/40-32

Found - Old 3" sq. Cedar post.

- Orig. 12" now 22" Cedar, alive, S.80°W., 11.9 ft.,
 shows good scar, do not open. Rescribe "T27S R2W
 S6 CS BT".
- Orig. 16" now 30" Cedar, alive, N.45°W., 21.1 ft.,
 shows scar. Do not open. Rescribe "T26S R2W S31
 CS BT".
- Orig. 12" now 24" Cedar, N.80°E., 23.8 ft., alive,
 previously opened, face rotted, no scribe.

Set Brass cap at cor. mkd: County Surveyors Office

S 31	S 32	T26S	
S 6	S 5	T27S	R2W

1967

New BTs- 11" Cedar N.69°E., 36.5 ft. mkd. T26S R2W S32 CSBT
 18" Cedar S.20°E., 24.8 ft. mkd. T27S R2W S5 CS BT.
 Corner lies at cutting corner, cut off in section 6.

Fd. DCSO BC & 4 BTs, set 6' steel post 2' north; by D.Edwards
 6/2010 - M160-76

Fd. BC, 2 BTs & 3 stumps by R. Rice 2/2011 - M162-6