

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A roothole, bears S.7°E., 11.9 ft., with a fallen, decayed fir snag, size indeterminate, lying uphill, with no marks visible.

A cedar, 27" dia., bears S.38°W., 13.9 ft., with a healed blaze.

A sawed fir stump, 26" dia., bears N.9°W., 18.5 ft., with a healed blaze.

and a bearing tree mkd. by Quibell

A cedar, 12" dia., bears N.75¼°E., 40.5 ft., with fragmentary scribe marks visible on partially healed double blazes.

and new accessories

A rebar, 30". long, 5/8" dia., driven 29". in the ground for a reference monument, bears N.72°45'42"E., 81.33 ft., with an aluminum cap mkd. RM T26S R2W 81.3 FT TO COR S29 2011, and an arrow pointing to the cor.

A rebar, 30". long, 5/8" dia., driven 29". in the ground for a reference monument, bears S.34°18'07"E., 75.46 ft., with an aluminum cap mkd. RM T26S R2W 75.5 FT TO COR S32 2011, and an arrow pointing to the cor.

A rebar, 30". long, 5/8" dia., 29". in the ground for a reference monument, bears N.51°21'50"W, 30.12 ft., with an aluminum cap mkd. RM T26S R2W 30.1 FT TO COR S30 2011, and an arrow pointing to the cor.

Corner is located 40 ft. N. of a gravel road, 13 ft. wide, bears N.80°E. and S.80°W, and further located 20 ft. W. of the gravel access road of a rock quarry, 12 ft. wide, bears N.35°E. and S.35°W.

1983 (CORS 96)

Latitude: 43°16'17.874"N Longitude: 122°58'14.858"W

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - 8/27/2020 - C.S. File 67/46-38

Found OK

Quibell's cedar (10" in 1981) gone - road work

Lat: 43.271636899 Long: -122.97080855

10/2020 Still ok after fire

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/4/2021 (Filed 11/18/2021) - C.S. File 67/51-4

Found - 2½" alum cap on ¾" iron pipe by Shrum 1963 (no record - stamped as per reported in 1981)

A roothole S.7°E., 11.9 ft. with fallen decayed Fir lying uphill. 1908 OBT

27" Cedar S.38°W., 13.9 ft. good scar. 1908 OBT

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

26" sawed Fir stump N.9°W., 18.5 ft. good scar. OBT
5/8" iron rod with alum. cap N.72°45'42"E., 81.33 ft.
marked RM T26S R2W 81.3 ft. to Cor 29 2011
5/8" iron rod with alum. cap S.34°18'07"E., 75.46 ft.
marked RM T26S R2W 75.5 ft. to Cor S 32 2011
5/8" iron rod with alum. cap N.51°21'50"W., 30.12 ft.
marked RM T26S R2W 30.1 ft. to Cor S 30 2011
All caps have arrows pointing to corner.
Steel fence post 2' East.
Note - Area burnt by Archie Fire 9/2020
Corner is 40' N of road & 20' West of road to rock
quarry.
Re-tag and re-flag accessories after fire.
Compass decl. 14½°E.
Lat: 43°16'17.91"N Long: 122°58'14.91"W