

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Page(s) 4245)

Set granite stone, 8x8x12" 8" in the ground for the 1/4 sec. cor. marked 1/4 on W face; from which

A cedar, 12" dia., bears S.58°E., 5 lks., mkd: 1/4 S29 BT.

A cedar, 10" dia., bears N.82°W., 26 lks., mkd: 1/4 S30 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - July 1967 - C.S. File 54/40-18

Found - Orig. corner stone 7"x8"x10", firmly set & faint "1/4" on W.

Orig. 12", now 20" Cedar, S.58°E., 3.3 ft. (face) Alive, shows good scar, do not open.

Orig. 10, now 21" Cedar, N.82°W., 17.2 ft. (face) alive, prev. opened & shows "1/4 S30 BT" scribe & we find chips with reverse scribe on ground.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T26S R2W (Reset cor. stone OFFICE 1967 1/4 S30|S29 along side)

New BTs- 10" hemlock N.70°W., 21.1 ft. mkd: 1/4 S30 CS BT.

7" hemlock N.55°E., 21.2 ft. mkd: 1/4 S29 CS BT.

Note - This corner lies on moderate SE slope approx. 400 ft. N of power line from river to top of Mt. along Bob Creek.

David Edwards - For: Seneca Jones Timber Co. - 1/2011 - C.S. File 65/74-1

Found - Brass cap

14" Hemlock N.55°E., 21.2'

25" Cedar S.58°E., 4.3'

25" Cedar N.82°W., 17.2' (face)

12" Hemlock N.70°w., 21.1'