

PRIMARY CORNER DESCRIPTION CC Secs. 17 & 18, South

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4216)

Set post, 4 ft. long, 4" sq., 24" in the ground for cor. of secs. 17, 18, 19, & 20, mkd T26S S17 on NE, R2W S20 on SE, S19 on SW & S18 on NW faces with 3 notches on S and 5 notches on East edges, from which
A cedar, 36" dia., bears N.30°E., 64 lks., mkd: T26S R2W S17 BT.
A hemlock, 10" dia., bears S.80°E., 55 lks., mkd: T26S R2W S20 BT.
A fir, 36" dia., bears S.75°W., 16 lks., mkd: T26S R2W S19 BT.
A cedar, 48" dia., bears N.50°W., 15 lks., mkd: T26S R2W S18 BT.

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Page(s) 4230)

The cor. secs. 17, 18, 19, & 20, which is a stake greatly decayed, marked & witnessed as described by the Surveyor General.
Set granite stone, 8x10x14", 10" in the ground for cor. secs. 18, 17, 19, & 20, marked with 4 notches on E & 3 notches on S edge.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4318 & 4319)

Page 4318
Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 17 & 18, with brass cap marked:
 T26S R2W
 S 18 | S 17
 1918
from which
A fir, 24" dia. bears N.18°E. 70 lks. mkd: T26S R2W S17 BT
A fir, 10" dia. bears N.4°W., 62 lks. mkd: T26S R2W S18 BT
Page 4319
The corresponding McQuinn corner, identified by Gibb & reestablished by me in 1916 as the cor. of secs. 17 & 18, bears S.45°02'E., 27.76 chs. I destroy marks on iron post.

continued next page

PRIMARY CORNER DESCRIPTION CC Secs. 17 & 18, South

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12745)

The cor. of secs. 17 & 18, only, on the N. bdy of sec. 19 monumented by Mensch in 1918, with an iron post, 2" dia., protruding 8" above ground, firmly set, with brass cap properly mkd., from which 1918 BTs

A fir, 36" dia., bears N.18°E., 70 lks., with a healed blaze.

A fir snag, 12" dia., bears N.4°W., 62 lks., with a healed blaze.

add one new BT

A fir, 16" dia. bears N.75°W. 54 lks. mkd: T26S R2W S18 BT

Weyerhaeuser corner report by Glen McChesney stamped by Frank O. Williams - 3/11/1975 - C.S. File 59/8-21

Found - 1918 GLO brass cap
36" fir, face healed over, BLM tag, N.19°E., 46.4 ft. center of tree measurement
10" fir snag, face healed over, N.2°W., 40.4 ft., center of tree measurement.
14" fir, face healed over, BLM tag, N.79°W., 35.5 ft. center of tree measurement.

This corner is common to Secs. 17 & 18 only; the closing corner of sections 19 & 20 bears N.87°01'E., 4.18 chs.

New - 32" R.Cedar, S.13°E., 4.6 ft., "W" nail & plate. Soon to be logged to NW, other quadrants virgin.

Douglas Co. Surveyors Office - A. Victor Cangie - G. Langlitz - D. Stewart - April 22, 1976 - C.S. 59/8-21

Found - A 1918 GLO brass cap properly stamped, in good condition.
A 36" now 38" Fir, bears N.18°W., 46.2 ft. with healed blaze alive and well.
A 12" Fir snag, bears N.1°W., (Rec N.4°W) 40.3 ft. with well healed blaze.
A 16" Fir, bears N.78°W., (rec. N.75°W) 35.6 ft. with well healed blaze. (See 1960 resurvey)

New BT- A 20" Red Cedar, bears S.24°W., 53.1 ft. marked "T26S R2W S19 CS BT" in a double blaze.