

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4220)

-----

Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on W face, from which:

A fir, 14" dia., bears S.80°E., 8 lks., mkd: 1/4 S BT.

A fir, 12" dia., bears N.35°W., 12 lks., mkd: 1/4 S BT.

---

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4317)

-----

The 1/4 cor. of secs. 7 & 8, which is a decayed post, witnessed as described by the surveyor general & which is verified as the orig. McQuinn cor. I perpetuate this cor. by setting an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 cor. of secs. 7 & 8 with brass cap mkd:

$\frac{1}{4}$   
 S 7 | S 8  
 1918

---

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12749)

-----

The 1/4 sec. cor. of secs. 7 & 8, remonumented by Mensch in 1918 with an iron post, 1" dia., protruding 12" above ground, firmly set, with brass cap (properly) mkd., from which the orig BTs

A rotted fir snag, 16" dia., bears S.72°E., 8 lks., with a partially opened blaze. (Rec. bearing S.80°E.)

A fir, 16" dia., bears N.33 1/2°W., 12 lks., with a healed blaze. (Rec. bearing N.35°W.)

and one new BT

A fir, 35" dia., bears N.59 3/4°E., 15 lks., mkd: 1/4 S8 BT.

---

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 5/12/2005 - C.S. File 67/10-24

-----

Found - 2 1/2" dia., BC on 1" O.D. iron pipe projecting 1 ft. above ground, loose, in low mound of rocks. BC (properly mkd) is dated 1918

16" now 20" D.Fir bears N.33 1/2°W., 8.6 ft. (rec. N.35 1/2°W. 7.9 ft. 1918) orig. BT. Fully healed single blaze is faint.

35" now 39" D.Fir bears N.59 3/4°E., 9.9 ft. agrees w/rec., fully healed single blaze vis. illegible bark scribe also visible. 1918 BT. cont.

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

|       |       |             |       |
|-------|-------|-------------|-------|
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |

A rotted Fir snag 17" dia., approx 11 ft. tall  
healed blaze vis. bears S.72°E., 6.1 ft. (rec.  
S.72°E., 5.3 ft. 1918) Orig. BT. Fits as face  
meas.

New - 8" dia., I.Cedar, pistol butted, double blazed &  
scribed "¼ S8 CS BT" bears N.47°E., 32.4 ft.  
8" dia., D.Fir, double blazed & scribed "¼ S7 CS  
BT" bears S.43½°W., 17.9 ft.

Note - Corner lies on steep SE'ly facing slope.  
Compass decl. 16¾°E.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral  
Surveyor, under Group No. 2923, surveyed July 2018/March  
2020- (DCSO records Vol. 59 Pages 24061-2)

-----

The ¼ sec. cor. of secs. 7 and 8, reported by Zirpel, Jr.,  
and Glenn in 1959; perpetuated by Smith, in 2005; monumented  
with an iron post, 1" dia., firmly set, projecting 12" above  
ground, in a collar of stone, with a brass cap (properly) mkd  
from which the remains of the bearing trees reported by  
Zirpel, Jr., and Glenn

A fir, 42" dia., bears N.59¾°E., 9.9 ft., with a healed  
blaze.

A decayed fir snag, 18" dia., bears S.72°E., 5.3 ft., with  
a healed double blaze. (Original)

A fir, 23" dia., bears N.33½°W., 7.9 ft., with a healed  
blaze. (Original)

and the bearing trees mkd. by Smith

A cedar, 9" dia., bears N.48°E., 32.3 ft., with scribe  
marks ¼ S8 CS BT visible on partially healed double  
blaze.

A fir, 9" dia., bears S.43½°W., 18.2 ft., with a healed  
double blaze.