

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4215)

Set post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd ¼ S on N face, from which

- A fir, 12" dia., bears N.10°W., 22 lks., mkd: ¼ S BT.
- A fir, 10" dia., bears S.31½°E., 14 lks., mkd: ¼ S BT.

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12743-4)

Point for the ¼ sec. cor. of secs. 4 & 5, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2½" dia., 8" in the ground to bedrock, & in a mound of stone, 3½ ft. base, to top, with brass cap marked:

T26S R2W
 ¼
 S 5|S 4
 1959

from which

- A hemlock, 12" dia., bears N.78°E., 16½ lks., mkd: T26S R2W S4 BT.
- A hemlock, 10" dia., bears S.83°W., 16 lks., mkd: ¼ S5 BT.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2923, surveyed July 2018/March 2020- (DCSO records Vol. 59 Pages 24060)

The ¼ sec. cor. of secs. 4 and 5, reported by Zirpel, Jr., and Glenn in 1959, monumented with an iron post, 2½" dia., firmly set, projecting 25" above ground, in a mound of stone, 3 ft. base, 12 ins. high, with a brass cap (properly) mkd. from which the remains of the bearing trees reported by Zirpel, Jr., and Glenn

- A hemlock snag, 17" dia., bears N.78°E., 10.9 ft., with a healed blaze.
- A hemlock, 15" dia., bears S.83°W., 10.6 ft., with a healed blaze.

and a new bearing tree

- A hemlock, 18" dia., bears S.76½°E., 9.3 ft., mkd. ¼ S4 BT

Ron Quimby - Crew: N. Fromdahl, L. Heddens & J. Ogden - 10/2020 - C.S. File 65/106-53

Found - BLM brass cap (properly mkd)
continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

<p>New -</p>	<p>17" burnt snag N.73°E., 10.9 ft. no scar (N.78°E., 10.9) 16" burnt Hemlock S.78°E., 9.3 ft. open scar nail in side of tree (no record) (9/29/2022 see above) 17" burnt Hemlock S.83°W., 10.6 ft. No visible scar. 5/8"x30" I.Rod with yellow plastic cap stamped "ie ENGINEERING" post along side. N.35°E., 7.1; S.70°E., 3.5; S.52°W., 3.6; N.38°E., 2.8</p>
<p>Note -</p>	<p>Area badly burnt 9/2020 Compass decl. 15½°E.</p>